
ELECTRIC MOTORS AND CONTROLS



こう こう こうこう こうこう こうこう こうこう

UGLY

Electric Motors and Controls



Printed in the U.S.A.

A note from the author ...

Ugly's Electric Motors and Controls is based on the 2008 NEC® and is designed to be used as a quick on-the-job reference in the electrical industry. We have tried to include the most commonly required information in an easy-to-read format.

We salute the National Fire Protection Association for their dedication to the protection of lives and property from fire and electrical hazards through the sponsorship of the National Electrical Code®.

NATIONAL ELECTRICAL CODE® and NEC® are registered trademarks of the National Fire Protection Association, Inc., Quincy, MA.



JONES AND BARTLETT PUBLISHERS

Sudbury, Massachusetts
TORONTO LONDON SINGAPORE

TABLE OF CONTENTS

THE LEFT-HAND RULE	1
MAGNETIC FIELD AROUND A COIL	2
ELECTROMAGNETIC INDUCTION	3
THE LEFT-HAND RULE FOR GENERATORS	4
BASIC MOTOR OPERATION	5
BASIC DC MOTOR: SPEED CONTROL	6
CALCULATING SYNCHRONOUS SPEED	7
CALCULATING RUNNING SPEED	7
AC MOTOR OPERATION AT OVER- AND UNDER-VOLTAGES	8
DC MOTOR OPERATION AT OVER- AND UNDER-VOLTAGES	9
MINIMUM DEPTH OF CLEAR WORKING SPACE IN FRONT	
OF ELECTRICAL EQUIPMENT	. 10
MINIMUM CLEARANCE OF LIVE PARTS	11
HORSEPOWER RATINGS FOR NEMA STARTERS	12
MAXIMUM HORSEPOWER	13
RUNNING OVERLOAD UNITS	14
MOTOR BRANCH-CIRCUIT PROTECTIVE DEVICES MAXIMUM	
RATING OR SETTING	15
FULL-LOAD CURRENT FOR DIRECT-CURRENT MOTORS	
IN AMPERES	16
FULL-LOAD CURRENT FOR SINGLE-PHASE ALTERNATING	
CURRENT MOTORS IN AMPERES	17
THREE-PHASE ALTERNATING CURRENT MOTORS FULL-LOAD	
CURRENT	18
FULL-LOAD CURRENT AND OTHER DATA FOR THREE-PHASE	
AC MOTORS	19
MOTOR AND MOTOR CIRCUIT CONDUCTOR	
PROTECTION	20
GENERAL MOTOR RULES	20
MOTOR BRANCH-CIRCUIT AND FEEDER EXAMPLE	21
GENERAL MOTOR APPLICATIONS	21
MAXIMUM MOTOR LOCKED-ROTOR CURRENT	22
MAXIMUM MOTOR LOCKED-ROTOR CURRENT IN AMPERES,	
TWO & THREE PHASE, DESIGN B, C, AND D	22
OHM'S LAW	23
ELECTRICAL FORMULAS FOR CALCULATING AMPERES,	
HORSEPOWER, KILOWATTS, AND KVA	25
TO FIND AMPERES	26
TO FIND HORSEPOWER	30
TO FIND WATTS	31
TO FIND KILOWATTS	32
TO FIND KILOVOLT-AMPERES	
KIRCHHOFF'S LAWS	33

TABLE OF CONTENTS (continued)

TO FIND INDUCTANCE	
INDUCTANCE (L)	
TO FIND IMPEDANCE	
IMPEDANCE (Z)	35
TO FIND REACTANCE	
REACTANCE (X)	36
SYNCHRONOUS SPEED	
SLIP	37
LOCKED-ROTOR CURRENT THREE PHASE	
LOCKED-ROTOR CURRENT SINGLE PHASE	
MOTOR FRAMES	
FRAME DIMENSIONS, IN INCHES	
FRAME LETTER DESIGNATIONS	
INSULATION CLASSES	41
COMMON ELECTRICAL DISTRIBUTION SYSTEMS	42
VOLTAGE DROP CALCULATIONS, INDUCTANCE NEGLIGIBLE	.44
SINGLE-PHASE CIRCUITS	44
THREE-PHASE CIRCUITS	44
VOLTAGE DROP CALCULATION EXAMPLES	45
SINGLE-PHASE VOLTAGE DROP	
THREE-PHASE VOLTAGE DROP	
MAXIMUM PERMISSIBLE CAPACITOR KVAR	.48
FOR USE WITH OPEN-TYPE THREE-PHASE SIXTY-CYCLE	40
INDUCTION MOTORS	.48
POWER-FACTOR CORRECTION	.49
POWER FACTOR AND EFFICIENCY EXAMPLE	.50
LOCKED-ROTOR CODE LETTERS	
SINGLE-PHASE MOTORS	.53
THREE-PHASE MOTORS	.53
THREE-PHASE AC MOTOR WINDINGS AND CONNECTIONS	.54
NEMA ENCLOSURE TYPES NONHAZARDOUS LOCATIONS	.55
NEMA ENCLOSURE TYPES HAZARDOUS LOCATIONS	oc.
U.S. WEIGHTS AND MEASURES	50
	.59
LINEAR MEASURES	.59 .59
MILE MEASUREMENTS	.59 .59 .59
MILE MEASUREMENTS	.59 .59 .59
MILE MEASUREMENTS	.59 .59 .59 .59
MILE MEASUREMENTS	.59 .59 .59 .59 .60
MILE MEASUREMENTS	.59 .59 .59 .60 .60
MILE MEASUREMENTS OTHER LINEAR MEASUREMENTS SQUARE MEASURES CUBIC OR SOLID MEASURES LIQUID MEASUREMENTS DRY MEASURES	.59 .59 .59 .60 .60
MILE MEASUREMENTS OTHER LINEAR MEASUREMENTS SQUARE MEASURES CUBIC OR SOLID MEASURES LIQUID MEASUREMENTS DRY MEASURES WEIGHT MEASUREMENTS (MASS)	.59 .59 .59 .60 .60 .61 .61
MILE MEASUREMENTS OTHER LINEAR MEASUREMENTS SQUARE MEASURES CUBIC OR SOLID MEASURES LIQUID MEASUREMENTS DRY MEASURES	.59 .59 .59 .60 .60 .61 .62 .63

TABLE OF CONTENTS (continued)


LINEAR MEASURES	.63
SQUARE MEASURES	
CUBIC MEASURES	.64
MEASURES OF WEIGHT	.65
MEASURES OF CAPACITY	
METRIC DESIGNATOR AND TRADE SIZES	.67
U.S. WEIGHT AND MEASURES/METRIC EQUIVALENT	
CHART	.67
EXPLANATION OF SCIENTIFIC NOTATION	
USEFUL CONVERSIONS/EQUIVALENTS	.68
DECIMAL EQUIVALENTS	.69
SINGLE-PHASE MOTORS	.71
DIRECT-CURRENT MOTORS	
MOTOR SELECTION CHECKLIST	.74
MOTOR SELECTION CRITERIA	.75
TYPICAL LOAD SERVICE FACTORS	
OVERCURRENT PROTECTION FOR TWO OR MORE MOTORS	.77
OVERCURRENT PROTECTION FOR MOTORS AND	
OTHER LOADS	.78
DETERMINING OVERLOAD SIZE	.79
DETERMINING CONTROLLER SIZE	
MOTORS 2 HORSEPOWER OR LESS AND 300 VOLTS OR LESS	81
DETERMINING CONDUCTOR SIZES FOR SINGLE-PHASE	
MOTORS	82
DETERMINING CONDUCTOR SIZES FOR ADJUSTABLE	
SPEED DRIVES	.83
MOTOR AND MOTOR-CIRCUIT CONDUCTOR PROTECTION	.83
GENERAL MOTOR RULES	
MOTOR BRANCH CIRCUIT AND FEEDER EXAMPLE	84
GENERAL MOTOR APPLICATIONS	.84
APPROXIMATE TORQUE FIGURES, COMPOUND DC MOTORS	86
HEATER CORRECTIONS FOR AMBIENT TEMPERATURES	
APPROXIMATE TORQUE FIGURES, AC MOTORS	
APPROXIMATE TORQUE FIGURES, WOUND ROTOR MOTORS	88
SIZING LOAD CONDUCTORS FROM GENERATORS	89
ELECTRICAL SAFETY DEFINITIONS	90
ELECTRICAL SAFETY CHECKLIST	93
ELECTRICAL SAFETY LOCKOUT-TAGOUT PROCEDURES	94
APPLICATION OF LOCKOUT-TAGOUT DEVICES	.94
REMOVAL OF LOCKOUT-TAGOUT DEVICES	.95
ELECTRICAL SAFETY SHOCK PROTECTION BOUNDARIES	
ELECTRICAL SAFETY HOW TO READ A WARNING LABEL	
PULLEY CALCULATIONS	.98
DETERMINING BELT LENGTH	99

TABLE OF CONTENTS (continued)


HORSEPOWER CAPACITIES99
GEAR SIZING100
DETERMINING SHAFT DIAMETER100
GEAR REDUCERS101
OUTPUT TORQUE101
OUTPUT SPEED101
OUTPUT HORSEPOWER101
MOTOR TORQUE102
TORQUE102
STARTING TORQUE102
CALCULATING COST OF OPERATING AN ELECTRICAL
APPLIANCE
ELECTRICAL SYMBOLS103
WIRING DIAGRAMS105
COMPLETE STOP-START SYSTEM WITH CONTROL
TRANSFORMER
HAND OFF AUTOMATIC CONTROL
JOGGING WITH CONTROL RELAY110
WIRING DIAGRAMS111
PLUGGING CIRCUIT113
TERMINAL DESIGNATIONS114
GENERATORS AND SYNCHRONOUS MOTORS114
COUNTER-EMF STARTING
DC MOTORS115
TWO-SPEED STARTING116
REDUCED-VOLTAGE STARTING
SYNCHRONOUS MOTOR



THE LEFT-HAND RULE



Any time an electrical current flows through a conductor, it creates a magnetic field around it. The left-hand rule identifies the directions of the current and the magnetic field. If you hold the conductor in your left hand, with your thumb pointing from the negative to the positive pole, the magnetic field around the conductor will always be in the direction your fingers point.



	At 10% Under-Voltage
Efficiency	-2%
Temperature	+18%
Current (full load)	+12%
Speed at full load	+1%
Torque	-20%
Power factor	-4%

	At 10% Over-Voltage
Efficiency	+1%
Temperature	-9%
Current (full load)	-7%
Speed at full load	-2%
Torque	+20%
Power factor	+4%

^{*} All figures approximate.



DC MOTOR OPERATION AT OVER-AND UNDER-VOLTAGES

	At 10% Un	der-Voltage	At 10% Over-Voltage		
Characteristic	Shunt	Compound	Shunt	Compound	
Speed	-5%	-6%	+5%	+6%	
Current	+12%	+12%	-8%	-8%	
Shunt Torque	-15%	-15%	+15%	+15%	
Field Temp	Increased	Decreased	Increased	Increased	
Commutator Temp	Increased	Increased	Decreased	Decreased	
Armature Temp	Increased	Increased	Decreased	Decreased	



MINIMUM DEPTH OF CLEAR WORKING SPACE IN FRONT OF ELECTRICAL EQUIPMENT

NOMINAL	Ten umanes	CONDITIONS	
VOLTAGE TO GROUND	1	2	3
VOLINGE TO STATE	Minim	num clear distance	e (feet)
0 - 150	3	3	3
151 - 600	3	3½	4
601 - 2500	3	4	5
2501 - 9000	4	5	6
9001 - 25,000	5	6	9
25,001 - 75 kV	6	8	10
Above 75 kV	8	10	12

NOTES:

Condition 1 = Live parts are exposed on one side of the working space only. Or: Live parts are exposed on both sides of the working space, but are all sufficiently guarded by insulating materials.

Condition 2 = Live parts are exposed on one side of the working space and grounded parts are exposed on the other side of the working space. Walls are considered to be grounded if made of concrete, brick, or tile.

Condition 3 = Live parts are exposed on both sides of the working space.



MINIMUM CLEARANCE OF LIVE PARTS

NOMINAL VOLTAGE	IMPULSE WITHSTAND B.I.L.		MINIMU	M CLEARAN INC	ICE OF LIVE PA HES	ARTS,
RATING	KV		PHASE-TO	D-PHASE	PHASE-TO-	GROUND
KV	OUTDOORS	INDOORS	OUTDOORS	INDOORS	OUTDOORS	INDOORS
2.4 - 4.16	95	60	7	4.5	6	3.0
7.2	95	75	7	5.5	6	4.0
13.8	110	95	12	7.5	7	5.0
14.4	110	110	12	9.0	7	6.5
23	150	125	15	10.5	10	7.5
34.5	150	150	15	12.5	10	9.5
	200	200	18	18.0	13	13.0
46	200	_	18	_	13	
	250	_ =	21	-	17	-
69	250	_	21	_	17	86 T = 38
	350	_	31	_	25	
115	550	-	53	-	42	
138	550	-	53	_	42	
	650	-12	63		50	#
161	650		63	-	50	-
	750	_	72		58	-
230	750	_	72	-	58	-
	900	_	89	_	71	
	1050	-	105	-	83	-

- The clearances listed above are for rigid parts and bare conductors, under what the NEC calls "favorable service conditions." Where there will be conductor movement or other complications will be present, the above clearances should be exceeded. Extra space should always be provided if possible.
- The impulse-withstand voltage is determined by a system's surge protective equipment.



HORSEPOWER RATINGS FOR NEMA STARTERS

NEMA Size	Volts (VAC)	Single Phase	Three Phase	Current Rating (Amperes)
	115	1/3		
	200		13/2	0
00	230	1	13/2	9
	460/575	AMON	2	
	115	1	-	
	200		3	
0	230	2	3	18
	460/575		5	
	115	2	9860	
	200		71/2	
1	230	3	71/2	27
	460/575	_	10	
	115	3	10	
1P		5		36
	230	5		
	115	0	10	
2	200	71/		45
	230	71/2	15	
	460/575		25	
	115	71/2	-	
3	200	000	-25	90
The state of	230	15	30	
	460/575	(manufic	50	
	200	-	40	
4	230	-	50	135
	460/575		100	
5	200	2000	75	270
9	230	A () [II]	100	210
	460/575	-	200	
	200		150	
6	230		200	540
	460/575	new -	400	
_	230		300	00
7	460/575	oses	600	90
NUIS CONTRACTOR	230		450	4045
8	460/575	water	400	1215
	460/575		900	
9	230	1000	800	2250

Reprinted from Miller, Charles R. *NFPA's Pocket Electrical References, First Edition.* Jones and Bartlett Publishers, 2007.

MAXIMUM HORSEPOWER

		80		Ė	Three-Phase Motors	se Motor	gn					
		Full- Voltag Startin	r ge ng	T,	Auto- Transformer Starting	er		Part- Winding Starting			Wye- Delta Starting	
NEMA	200 VAC	230 VAC	460/575 VAC	200 VAC	230 VAC	460/ 575 VAC	200 VAC	230 VAC	460/ 575 VAC	200 VAC	230 VAC	460/ 575 VAC
8	11%	11/2	2	Depart.	-	-	STATE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN CO	-	2000	, market 1	-	-
0	හ	3	2	1	1	1	1	1	1	1	1	1
-	71/2	7%	10	71%	77%	10	10	10	15	10	10	±
23	10	15	25	10	15	25	20	25	40	20	25	40
es	25	30	50	25	30	20	9	50	75	40	50	75
4	40	20	100	40	50	100	75	7.5	150	09	75	150
S.	75	100	200	75	100	200	150	150	350	150	150	300
g	150	200	400	150	200	400	1	300	009	300	350	700
1	ł	300	009	-	300	009	1	450	006	200	200	1000
00	1	450	900	-	450	006	1	700	1400	750	800	1500
ග	1	800	1600	1	800	1600	1	1300	2600	1500	1500	3000

Reprinted from Miller, Charles R. NFPA's Pocket Electrical References, First Edition. Jones and Bartlett Publishers, 2007.



RUNNING OVERLOAD UNITS

TYPE OF MOTOR	SUPPLY	NUMBER AND LOCATION OF OVERLOAD UNITS
1-phase AC or DC	2-wire 1-phase AC or DC ungrounded	1 overload in either conductor
1-phase AC or DC	2-wire1-phase AC or DCone conductor ungrounded	1 overload in ungrounded conductor
1-phase AC or DC	3-wire 1-phase AC or DC grounded neutral conductor	1 overload in either ungrounded conductor
1-phase AC	any 3-phase	1 overload in ungrounded conductor
2-phase AC	3-wire 2-phase AC ungrounded	2 overloads, one in each phase
2-phase AC	3-wire2-phase ACone conductor grounded	2 overloads in ungrounded conductors
2-phase AC	4-wire2-phase ACgrounded or ungrounded	2 overloads, one per phase in ungrounded conductors
2-phase AC	5-wire2-phase ACgrounded neutral or ungrounded	2 overloads, one per phase in any ungrounded phase wire
3-phase AC	any 3-phase	3 overloads, one in each phase*

^{*} Exception: Where protected by other approved means.



Type of Motor	Nontime Delay Fuse	Dual- Element (Time- Delay) Fuse	Instan- taneous Trip Breaker	Inverse Time Breaker
AC polyphase motors other than wound rotor	300% FLC	175% FLC	800% FLC	250% FLC
DC (constant voltage)	150% FLC	150% FLC	250% FLC	150% FLC
Design B energy-efficient	300% FLC	175% FLC	1100% FLC	250% FLC
Single-phase motors	300% FLC	175% FLC	800% FLC	250% FLC
Squirrel cage—other than Design B energy-efficient	300% FLC	175% FLC	800% FLC	250% FLC
Synchronous	300% FLC	175% FLC	800% FLC	250% FLC
Wound rotor	150% FLC	150% FLC	800% FLC	150% FLC

- There are exceptions to this chart. See NEC Sections 430.52-430.54.
- · Nontime Delay Fuse = Class CC fuses.
- For nonadjustable inverse time circuit breakers, see NEC Section 430.52.
- For low-torque, low-speed, synchronous motors that drive reciprocating compressors, pumps, or similar loads, and which start unloaded, fuse or circuit-breaker settings need not exceed 200% of full-load current.



FULL-LOAD CURRENT FOR DIRECT-CURRENT MOTORS IN AMPERES

Average DC Quantity	Armature Voltage Rating for Motors Running at Base Speed							
HP	90V	120V	180V	240V	500V			
1/4	4.0	3.1	2.0	1.6	oli in Euri			
1/3	5.2	4.1	2.6	2.0	-			
1/2	6.8	5.4	3.4	2.7	-			
3/4	9.6	7.6	4.8	3.8	-			
1	12.2	9.5	6.1	4.7	_			
11/2	## Z # 1	13.2	8.3	6.6				
2	-	17	10.8	8.5	-			
3	- 1	25	16	12.2				
5		40	27	20	ne En-			
71/2		58	-	29	13.6			
10		76		38	18			
15	-	-	_	55	27			
20	-	_		72	34			
25	_	10 to <u>1</u> 2 to 10		89	43			
30		-		106	51			
40	_	-	4670 <u>– 1</u> 900)	140	67			
50	-			173	83			
60	_	_		206	99			
75	_	-		255	123			
100	_	-	<u>.</u>	341	164			
125	_	-	-	425	205			
150	_	-		506	246			
200	-	-	-	675	330			



FULL-LOAD CURRENT FOR SINGLE-PHASE ALTERNATING **CURRENT MOTORS IN AMPERES**

HP	115V	200V	208V	230V
1/4	5.8	3.3	3.2	2.9
1/3	7.2	4.1	4.0	3.6
1/2	9.8	5.6	5.4	4.9
3/4	13.8	7.9	7.6	6.9
1	16	9.2	8.8	8.0
11/2	20	11.5	11	10
2	24	13.8	13.2	12
3	34	19.6	18.7	17
5	56	32.2	30.8	28
71/2	80	46	44	40
10	100	57.5	55	50

The voltages listed are rated motor voltages. The listed currents are for system voltage ranges of 110 to 120 and 220 to 240.

P

THREE-PHASE ALTERNATING CURRENT MOTORS FULL-LOAD CURRENT

		Induction Type Squirrel-Cage and Wound-Rotor Amperes						Synchronous Type Unity Power Factor* Amperes			
HP	115V	200V	208V	230V	460V	575V	2300V	230V	460V	575V	2300V
1/2	4.4	2.5	2.4	2.2	1.1	0.9	_	-	_	2-2	_
3/4	6.4	3.7	3.5	3.2	1.6	1.3		-	-	-	
1	8.4	4.8	4.6	4.2	2.1	1.7	-	_	-	-	-
11/2	12.0	6.9	6.6	6.0	3.0	2.4	-	-	_	_	-
2	13.6	7.8	7.5	6.8	3.4	2.7	_	-	_	-	_
3	-	11.0	10.6	9.6	4.8	3.9	-	-	-	_	_
5	_=	17.5	16.7	15.2	7.6	6.1	_	-		_	_
71/2	<u> </u>	25.3	24.2	22	11	9	-	-	_	E-	-
10	_	32.2	30.8	28	14	11	_	_	_	-	-
15	_	48.3	46.2	42	21	17	_	_	/ - ·	_	-
20	- T	62.1	59.4	54	27	22		-	H1=11	_	-
25	-	78.2	74.8	68	34	27	_	53	26	21	-
30	-	92	88	80	40	32	_	63	32	26	_
40		120	114	104	52	41	_	83	41	33	-
50	-	150	143	130	65	52	_	104	52	42	-
60	-	177	169	154	77	62	16	123	61	49	12
75	-	221	211	192	96	77	20	155	78	62	15
100	-	285	273	248	124	99	26	202	101	81	20
125		359	343	312	156	125	31	253	126	101	25
150	_	414	396	360	180	144	37	302	151	121	30
200	_	552	528	480	240	192	49	400	201	161	40
250	_	_	-	_	302	242	60		- I	-	
300		_	_	_	361	289	72	-	_	-	-
350	-	_	_	-	414	336	83		_	_	-
400	-	_	_	-	477	382	95	_	_	-	_
450	-	_	-	_	515	412	103	- 0		-	-

The voltages listed are rated motor voltages. The currents listed are for system voltage ranges of 110 to 120, 220 to 240, 440 to 480, and 550–600 volts.

^{*} Multiply by 1.1 and 1.25 for 90- and 80-percent power factor, respectively.

M

FULL-LOAD CURRENT AND OTHER DATA FOR THREE-PHASE AC MOTORS

	OTOR SEPOWER	MOTOR AMPERE	SIZE BREAKER	SIZE STARTER	HEATER AMPERE	SIZE WIRE	SIZE CONDUIT
1/2	230V	2.2	15	00	2.530	12	3/4"
	460	1.1	15	00	1.265	12	3/4"
3/4	230	3.2	15	00	3.680	12	3/4
	460	1.6	15	00	1.840	12	3/4
1	230	4.2	15	00	4.830	12	3/4
	460	2.1	15	00	2.415	12	3/4
11/2	230	6.0	15	00	6.900	12	3/4
	460	3.0	15	00	3.450	12	3/4
2	230	6.8	15	0	7.820	12	3/4
	460	3.4	15	00	3.910	12	3/4
3	230	9.6	20	0	11.040	12	3/4
	460	4.8	15	0	5.520	12	3/4
5	230	15.2	30	1	17.480	12	3/4
	460	7.6	15	0	8.740	12	3/4
71/2	230	22	45	1	25.300	10	3/4
	460	11	20	1	12.650	12	3/4
10	230	28	60	2	32.200	10	3/4
	460	14	30	1	16.100	12	3/4
15	230	42	70	2	48.300	6	1
	460	21	40	2	24.150	10	3/4
20	230	54	100	3	62.100	4	1
	460	27	50	2	31.050	10	3/4
25	230	68	100	3	78.200	4	1½
	460	34	50	2	39.100	8	Te 1 have
30	230	80	125	3	92.000	3	1½
	460	40	70	3	46.000	8	1
40	230	104	175	100	119.600	1	1½
	460	52	100	3	59.800	6	1
50	230	130	200	2,12	149.500	00	2
	460	65	150	3	74.750	4	11/2

Overcurrent device may have to be increased due to starting current and load conditions. See NEC 430–52, Table 430–52. Wire size based on 75°C terminations and 75°C insulation.

^{**} Overload heater must be based on motor nameplate & sized per NEC 430-32.

^{***} Conduit size based on Rigid Metal Conduit with some spare capacity. For minimum size & other conduit types, see NEC Appendix C.



FULL-LOAD CURRENT AND OTHER DATA FOR THREE-PHASE AC MOTORS

MOT HORSE	Www.dated.coventsc	MOTOR AMPERE	SIZE BREAKER	SIZE STARTER	HEATER AMPERE **	SIZE WIRE	SIZE CONDUIT
60	230V	154	250	5	177.10	000	2"
	460	77	200	4	88.55	3	11/2
75	230	192	300	5	220.80	250 _{kcmil}	21/2
	460	96	200	4	110.40	1	11/2
100	230	248	400	5	285.20	350 _{kcmil}	3
	460	124	200	4	142.60	2/0	2
125	230	312	500	6	358.80	600 _{kcmil}	31/2
	460	156	250	5	179.40	000	2
150	230	360	600	6	414.00	700 _{kcmil}	4
	460	180	300	5	207.00	0000	21/2

Motor and Motor Circuit Conductor Protection

Motors can have large starting currents three to five times or more than that of the actual motor current. In order for motors to start, the motor and motor circuit conductors are allowed to be protected by circuit breakers and fuses at values that are higher than the actual motor and conductor ampere ratings. These larger overcurrent devices do not provide overload protection and will only open upon short circuits or ground faults. Overload protection must be used to protect the motor based on the actual nameplate amperes of the motor. This protection is usually in the form of heating elements in manual or magnetic motor starters. Small motors such as waste disposal motors have a red overload reset button built into the motor.

General Motor Rules

- Use Full-Load Current from tables instead of nameplate.
- Branch-Circuit Conductors Use 125% of Full-Load Current to find conductor size.
- Branch-Circuit OCP Size Use percentages given in tables for Full-Load Current.
- Feeder Conductor Size 125% of largest motor and sum of the rest.
- Feeder OCP Use largest OCP plus rest of Full-Load Currents



MOTOR BRANCH-CIRCUIT AND FEEDER EXAMPLE

General Motor Applications

Branch-Circuit Conductors: Use Full-Load Three-Phase Currents; From *NEC* Table 430.250, 50 HP 480 volt Three-Phase motor design B, 75 degree terminations = 65 Amperes 125% of Full-Load Current [*NEC* 430.22(A)] 125% of 65 A = **81.25 Amperes** Conductor Selection Ampacity

Branch-Circuit Overcurrent Device: NEC 430.52 (C1) (Branch-Circuit Short Circuit and Ground-Fault Protection) Use percentages given in NEC 430.52 for Type of circuit breaker or fuse used.

50 HP 480 V 3 Ph Motor = 65 Amperes.

Nontime Fuse = 300%.

300% of 65A = 195 A. *NEC* 430.52(C1)(EX1) Next size allowed *NEC* 240.6A = 200 Ampere Fuse.

Feeder Connectors: For 50 HP and 30 HP 480 Volt Three-Phase design B motors on same feeder Use 125% of largest full-load current and 100% of rest. (*NEC* 430.24) 50 HP 480 V 3 Ph Motor = 65A; 30 HP 480 V 3 Ph Motor = 40A (125% of 65A) + 40A = 121.25 A Conductor Selection Ampacity

Feeder Overcurrent Device: NEC 430.62(A)

(Feeder short circuit and ground-fault protection)
Use largest overcurrent protection device <u>plus</u> full-load currents of the rest of the motors.

50 HP = 200 A fuse (65 FLC) 30 HP = 125 A fuse (40 FLC)

200 A fuse + 40 A (FLC) = 240 A. Do not exceed this value on feeder. Go down to a **225 A** fuse.



MAXIMUM MOTOR LOCKED-ROTOR CURRENT*

HP	115V	208V	230V	HP	115V	208V	230V
1/2	58.8	32.5	29.4	3	204	113	102
3/4	82.8	45.8	41.4	5	336	186	168
1	96	53	48	71/2	480	265	240
11/2	120	66	60	10	600	332	300
2	144	80	72	NAME OF TAXABLE PARTY.		125 T27 (8 T0)	

Adapted from NEC® Table 430.251(A).

^{*} Conversion Table for Selection of Disconnecting Means and Controllers as Determined from Horsepower and Voltage Rating. For use only with 430.110, 440.12, 440.41 and 455.8(C).



MAXIMUM MOTOR LOCKED-ROTOR CURRENT IN AMPERES, TWO & THREE PHASE, DESIGN B, C, AND D **

HP	115V	200V	208V	230V	460V	575V
1/2	40	23	22.1	20	10	8
3/4	50	28.8	27.6	25	12.5	10
1	60	34.5	33	30	15	12
11/2	80	46	44	40	20	16
2	100	57.5	55	50	25	20
3		73.6	71	64	32	25.6
5	_	105.8	102	92	46	36.8
71/2	-	146	140	127	63.5	50.8
10	-	186.3	179	162	81	64.8
15	-	267	257	232	116	93
20	-	334	321	290	145	116
25	-	420	404	365	183	146
30	-	500	481	435	218	174
40	_	667	641	580	290	232
50	-	834	802	725	363	290
60	-	1001	962	870	435	348
75	_	1248	1200	1085	543	434
100	-	1668	1603	1450	725	580
125	_	2087	2007	1815	908	726
150	_	2496	2400	2170	1085	868
200	_	3335	3207	2900	1450	1160

Adapted from NEC® Table 430.251(B).

^{**} Conversion Table for Selection of Disconnecting Means and Controllers as Determined from Horsepower and Voltage Rating and Design Letter. For use only with 430.110, 440.12, 440.41 and 455.8(C).



OHM'S LAW

The rate of the flow of the current is equal to electromotive force divided by resistance.

I = Intensity of Current = Amperes

E = Electromotive Force = Volts

R = Resistance = Ohms

P = Power = Watts


The three basic Ohm's Law formulas are:

$$I = \frac{E}{R}$$

$$I = \frac{E}{R}$$
 $R = \frac{E}{I}$

$$E = I \times R$$

Below is a chart containing the formulas related to Ohm's Law. To use the chart, from the center circle, select the value you need to find, I (Amps), R (Ohms), E (Volts) or P (Watts). Then select the formula containing the values you know from the corresponding chart quadrant.



Example:

An electric appliance is rated at 1200 Watts, and is connected to 120 Volts. How much current will it draw?

$$Amperes = \frac{Watts}{Volts}$$

Amperes =
$$\frac{\text{Watts}}{\text{Volts}}$$
 $I = \frac{P}{F}$ $I = \frac{1200}{120} = 10 \text{ A}$

What is the Resistance of the same appliance?

$$Ohms = \frac{Volts}{Amperes}$$

$$R = \frac{E}{I}$$
 $R = \frac{120}{10} = 12 \Omega$

OHM'S LAW

In the preceding example, we know the following values:

$$I = amps = 10$$

$$R = ohms = 12\Omega$$

$$E = volts = 120$$

$$P = watts = 1200$$

We can now see how the twelve formulas in the Ohm's Law chart can be applied.

AMPS =
$$\sqrt{\frac{\text{WATTS}}{\text{OHMS}}}$$

AMPS =
$$\sqrt{\frac{\text{WATTS}}{\text{OHMS}}}$$
 I = $\sqrt{\frac{P}{R}}$ = $\sqrt{\frac{1200}{12}}$ = $\sqrt{100}$ = 10A

$$AMPS = \frac{WATTS}{VOLTS}$$

$$I = \frac{P}{E} = \frac{1200}{120} = 10A$$

$$AMPS = \frac{VOLTS}{OHMS}$$

$$I = \frac{E}{R} = \frac{120}{12} = 10A$$

WATTS =
$$\frac{\text{VOLTS}^2}{\text{OHMS}}$$

$$P = \frac{E^2}{R} = \frac{120^2}{12} = \frac{14,400}{12} = 1200W$$

WATTS = VOLTS
$$\times$$
 AMPS P = E \times I = 120 \times 10 = 1200W

$$= \mathbf{E} \times \mathbf{I} = 120 \times 10 = 1200 \text{W}$$

WATTS =
$$AMPS^2 \times OHMS$$

WATTS = AMPS² × OHMS P =
$$I^2$$
 × R = $100 \times 12 = 1200$ W

VOLTS =
$$\sqrt{\text{WATTS}} \times \text{OHMS}$$

VOLTS =
$$\sqrt{\text{WATTS} \times \text{OHMS}}$$
 E = $\sqrt{P \times R}$ = $\sqrt{1200 \times 12}$ = $\sqrt{14,400}$ = 120V

$$VOLTS = AMPS \times OHMS$$

$$E = I \times R = 10 \times 12 = 120V$$

$$VOLTS = \frac{WATTS}{AMPS}$$

$$E = \frac{P}{I} = \frac{1200}{10} = 120V$$

OHMS =
$$\frac{\text{VOLTS}^2}{\text{WATTS}}$$

$$\mathbf{R} = \frac{\mathbf{E}^2}{\mathbf{P}} = \frac{120^2}{1,200} = \frac{14,400}{1,200} = 12\Omega$$

$$OHMS = \frac{WATTS}{AMPS^2}$$

$$R = \frac{P}{I^2} = \frac{1200}{100} = 12\Omega$$

$$OHMS = \frac{VOLTS}{AMPS}$$

$$R = \frac{E}{I} = \frac{120}{10} = 12\Omega$$





ELECTRICAL FORMULAS FOR CALCULATING AMPERES, HORSEPOWER, KILOWATTS, AND KVA

TO FIND	DIRECT		ALTERNATING CURRENT					
1011112	CURRENT	SINGLE PHASE	TWO PHASE-FOUR WIRE	THREE PHASE				
AMPERES When "HP" IS Known	HP x 746 E x %EFF	HP x 746 E x %EFF x PF	HP x 746 E x %EFF x PF x 2	HP x 746 E x %EFF x PF x 1.73				
AMPERES WHEN "KW" IS KNOWN	KW x 1000	KW x 1000 E x PF	KW x 1000 E x PF x 2	KW x 1000 E x PF x 1.73				
AMPERES WHEN "KVA" IS KNOWN		KVA x 1000	KVA x 1000 E x 2	KVA x 1000 E x 1.73				
KILOWATTS (True Power)	E x I 1000	Exix PF 1000	Exlx PF x 2 1000	Exix PF x 1.73				
KILOVOLT-AM- PERES "KVA" (Apparent Power	E = -0	E x I	E x l x 2	Exix 1.73				
HORSEPOWER	Exix %EFF 746	E x I x %EFF x PF 746	E x I x %EFF x PF x 2 746	E x l x %EFF x PF x 1.73 746				

PERCENT EFFICIENCY = % EFF = OUTPUT (WATTS)

POWER FACTOR = PF = POWER USED (WATTS)

REPARENT POWER KVÄ

NOTE: DIRECT CURRENT FORMULAS DO NOT USE (PF, 2, OR 1.73) SINGLE PHASE FORMULAS DO NOT USE (2 OR 1.73) TWO PHASE - FOUR WIRE FORMULAS DO NOT USE (1.73) THREE PHASE FORMULAS DO NOT USE (2)

E = VOLTS I = AMPERES W = WATTS



DIRECT CURRENT:

A. When HORSEPOWER is known:

AMPERES =
$$\frac{\text{HORSEPOWER x 746}}{\text{VOLTS x EFFICIENCY}}$$
 or I = $\frac{\text{HP x 746}}{\text{E x \%EFF}}$

What current will a travel-trailer toilet draw when equipped with a 12 volt, 1/8 HP motor, having a 96% efficiency rating?

$$I = \frac{HP \times 746}{E \times \%EFF} = \frac{746 \times 1/8}{12 \times 0.96} = \frac{93.25}{11.52} = 8.09 \text{ AMPS}$$

B. When KILOWATTS are known:

AMPERES =
$$\frac{\text{KILOWATTS x 1000}}{\text{VOLTS}}$$
 or I = $\frac{\text{KW x 1000}}{\text{E}}$

A 75 KW, 240 Volt, direct-current generator is used to power a variable-speed conveyor belt at a rock crushing plant.

Determine the current.

$$I = \frac{KW \times 1000}{F} = \frac{75 \times 1000}{240} = 312.5 \text{ AMPS}$$

SINGLE PHASE:

A. When WATTS, VOLTS, AND POWER FACTOR are known:

AMPERES =
$$\frac{\text{WATTS}}{\text{VOLTS x POWER FACTOR}}$$
 or $\frac{\text{P}}{\text{E x PF}}$

Determine the current when a circuit has a 1500 watt load, a power factor of 86%, and operates from a single-phase 230 volt source.

$$I = \frac{1500}{230 \times 0.86} = \frac{1500}{197.8} = 7.58 \text{ AMPS}$$



TO FIND AMPERES

SINGLE PHASE:

B. When HORSEPOWER is known:

$$AMPERES = \frac{HORSEPOWER \times 746}{VOLTS \times EFFICIENCY \times POWER FACTOR}$$

Determine the amp load of a single-phase, 1/2 HP, 115 volt motor. The motor has an efficiency rating of 92%, and a power factor of 80%.

$$I = \frac{HP \times 746}{E \times \%EFF \times PF} = \frac{1/2 \times 746}{115 \times 0.92 \times 0.80} = \frac{373}{84.64}$$

I = 4.4 AMPS

C. When KILOWATTS are known:

AMPERES =
$$\frac{\text{KILOWATTS x 1000}}{\text{VOLTS x POWER FACTOR}}$$
 or I = $\frac{\text{KW x 1000}}{\text{E x PF}}$

A 230 volt single-phase circuit has a 12KW power load, and operates at 84% power factor. Determine the current.

$$I = \frac{KW \times 1000}{E \times PF} = \frac{12 \times 1000}{230 \times 0.84} = \frac{12,000}{193.2} = 62 \text{ AMPS}$$

D. When KILOVOLT-AMPERE is known:

AMPERES =
$$\frac{\text{KILOVOLT-AMPERE x 1000}}{\text{VOLTS}}$$
 or $I = \frac{\text{KVA x 1000}}{\text{E}}$

A 115 volt, 2 KVA, single-phase generator operating at full load will deliver 17.4 AMPERES. (Prove.)

$$I = \frac{2 \times 1000}{115} = \frac{2000}{115} = 17.4 \text{ AMPS}$$

REMEMBER:

By definition, amperes is the rate of the flow of the current.



TO FIND AMPERES

THREE PHASE:

A. When WATTS, VOLTS, AND POWER FACTOR are known:

AMPERES =
$$\frac{\text{WATTS}}{\text{VOLTS x POWER FACTOR x 1.73}}$$

or
$$I = \frac{P}{F \times PF \times 1.73}$$

Determine the current when a circuit has a 1500 watt load, a power factor of 86%, and operates from a three-phase, 230 volt source.

$$I = \frac{P}{E \times PF \times 1.73} = \frac{1500}{230 \times 0.86 \times 1.73} = \frac{1500}{342.2}$$

I = 4.4 AMPS

B. When HORSEPOWER is known:

or
$$I = \frac{HP \times 746}{E \times \%EFF \times PF \times 1.73}$$

Determine the amp load of a three-phase, 1/2 HP, 230 volt motor. The motor has an efficiency rating of 92%, and a power factor of 80%.

$$I = \frac{\text{HP x 746}}{\text{E x \%EFF x PF x 1.73}} = \frac{1/2 \times 746}{230 \times .92 \times .80 \times 1.73}$$
$$= \frac{373}{293} = 1.27 \text{ AMPS}$$

M

TO FIND AMPERES

THREE PHASE:

C. When KILOWATTS are known:

or
$$I = \frac{KW \times 1000}{E \times PF \times 1.73}$$

A 230 volt, three-phase circuit, has a 12KW power load, and operates at 84% power factor. Determine the current.

$$I = \frac{KW \times 1000}{E \times PF \times 1.73} = \frac{12,000}{230 \times 0.84 \times 1.73} = \frac{12,000}{334.24}$$

I = 36 AMPS

D. When KILOVOLT-AMPERE is known:

AMPERES =
$$\frac{\text{KILOVOLT-AMPERE x 1000}}{\text{E x 1.73}} = \frac{\text{KVA x 1000}}{\text{E x 1.73}}$$

A 230 volt, 4 KVA, three-phase generator operating at full load will deliver 10 AMPERES. (Prove.)

$$I = \frac{\text{KVA x 1000}}{\text{E x 1.73}} = \frac{4 \times 1000}{230 \times 1.73} = \frac{4000}{397.9}$$

I = 10 AMPS



TO FIND HORSEPOWER

DIRECT CURRENT:

A 12 volt motor draws a current of 8.09 amperes, and has an efficiency rating of 96%. Determine the horsepower.

$$HP = \frac{E \times I \times \%EFF}{746} = \frac{12 \times 8.09 \times 0.96}{746} = \frac{93.19}{746}$$

$$HP = 0.1249 = 1/8 HP$$

SINGLE PHASE:

$$HP = \frac{\text{VOLTS x AMPERES x EFFICIENCY x POWER FACTOR}}{746}$$

A single-phase, 115 volt (AC) motor has an efficiency rating of 92%, and a power factor of 80%. Determine the horsepower if the amp load is 4.4 amperes.

$$HP = \frac{E \times I \times \%EFF \times PF}{746} = \frac{115 \times 4.4 \times 0.92 \times 0.80}{746}$$

$$HP = \frac{372.416}{746} = 0.4992 = 1/2 HP$$

THREE PHASE:

$$HP = \frac{\text{VOLTS x AMPERES x EFFICIENCY x POWER FACTOR x 1.73}}{746}$$

A three-phase, 460 volt motor draws a current of 52 amperes. The motor has an efficiency rating of 94%, and a power factor of 80%. Determine the horsepower.

$$HP = \frac{E \times I \times \%EFF \times PF \times 1.73}{746} = \frac{460 \times 52 \times 0.94 \times 0.80 \times 1.73}{746}$$

$$HP = 41.7 HP$$



TO FIND WATTS

The electrical power in any part of a circuit is equal to the current in that part multiplied by the voltage across that part of the circuit.

A watt is the power used when one volt causes one ampere to flow in a circuit.

One horsepower is the amount of energy required to lift 33,000 pounds, one foot, in one minute. The electrical equivalent of one horsepower is 745.6 watts. One watt is the amount of energy required to lift 44.26 pounds, one foot, in one minute. Watts is power, and power is the amount of work done in a given time.

When VOLTS AND AMPERES are known:

POWER (WATTS) = VOLTS x AMPERES

A 120 volt AC circuit draws a current of 5 amperes. Determine the power consumption.

 $P = E \times I = 120 \times 5 = 600 \text{ WATTS}$

We can now determine the resistance of this circuit.

POWER = RESISTANCE x (AMPERES)²

 $P = R \times I^2$ or $600 = R \times 25$ divide both sides of equation by 25

$$\frac{600}{25}$$
 = R or R = 24 OHMS

10

POWER =
$$\frac{(\text{VOLTS})^2}{\text{RESISTANCE}}$$
 or $P = \frac{E^2}{R}$ or $600 = \frac{120^2}{R}$

$$R \times 600 = 120^2$$
 or $R = \frac{14,400}{600} = 24 \text{ OHMS}$

NOTE: REFER TO THE FORMULAS OF THE OHM'S LAW CHART ON PAGE 24



TO FIND KILOWATTS

DIRECT CURRENT:

$$KILOWATTS = \frac{VOLTS \times AMPERES}{1000}$$

A 120 volt (DC) motor draws a current of 40 amperes. Determine the kilowatts.

$$KW = \frac{E \times I}{1000} = \frac{120 \times 40}{1000} = \frac{4800}{1000} = 4.8 \text{ KW}$$

SINGLE PHASE:

KILOWATTS =
$$\frac{\text{VOLTS x AMPERES x POWER FACTOR}}{1000}$$

A single-phase, 115 volt (AC) motor draws a current of 20 amperes, and has a power-factor rating of 86%. Determine the kilowatts.

KW =
$$\frac{\text{E x I x PF}}{1000}$$
 = $\frac{115 \times 20 \times 0.86}{1000}$ = $\frac{1978}{1000}$ = 1.978 = 2KW

THREE PHASE:

KILOWATTS =
$$\frac{\text{VOLTS x AMPERES x POWER FACTOR x 1.73}}{1000}$$

A three-phase, 460 volt (AC) motor draws a current of 52 amperes, and has a power-factor rating of 80%. Determine the kilowatts.

$$KW = \frac{E \times I \times PF \times 1.73}{1000} = \frac{460 \times 52 \times 0.80 \times 1.73}{1000}$$
$$= \frac{33,105}{1000} = 33.105 = 33KW$$



TO FIND KILOVOLT-AMPERES

SINGLE PHASE:

A single-phase, 240 volt generator delivers 41.66 amperes at full load. Determine the kilovolt-amperes rating.

$$KVA = \frac{E \times I}{1000} = \frac{240 \times 41.66}{1000} = \frac{10,000}{1000} = 10 \text{ KVA}$$

THREE PHASE:

KILOVOLT-AMPERES =
$$\frac{\text{VOLTS x AMPERES x 1.73}}{1000}$$

A three-phase, 460 volt generator delivers 52 amperes. Determine the kilovolt-amperes rating.

$$KVA = \frac{E \times I \times 1.73}{1000} = \frac{460 \times 52 \times 1.73}{1000} = \frac{41,382}{1000}$$

$$= 41.382 = 41 \text{ KVA}$$

NOTE: KVA = APPARENT POWER = POWER BEFORE USED, SUCH AS THE RATING OF A TRANSFORMER.

Kirchhoff's Laws

FIRST LAW (CURRENT):

THE SUM OF THE CURRENTS ARRIVING AT ANY POINT IN A CIRCUIT MUST EQUAL THE SUM OF THE CURRENTS LEAVING THAT POINT.

SECOND LAW (VOLTAGE):

THE TOTAL VOLTAGE APPLIED TO ANY CLOSED CIRCUIT PATH IS ALWAYS EQUAL TO THE SUM OF THE VOLTAGE DROPS IN THAT PATH.

OR

THE ALGEBRAIC SUM OF ALL THE VOLTAGES ENCOUNTERED IN ANY LOOP EQUALS ZERO.



TO FIND INDUCTANCE

Inductance (L):

Inductance is the production of magnetization of electrification in a body by the proximity of a magnetic field or electric charge, or of the electric current in a conductor by the variation of the magnetic field in its vicinity. Expressed in Henrys.

A. To find the total inductance of coils connected in series.

$$L_T = L_1 + L_2 + L_3 + L_4$$

Determine the total inductance of four coils connected in series. Each coil has an inductance of four Henrys.

$$L_T = L_1 + L_2 + L_3 + L_4$$

= 4 + 4 + 4 + 4 = 16 Henrys

B. To find the total inductance of coils connected in parallel.

$$\frac{1}{L_T} = \frac{1}{L_1} + \frac{1}{L_2} + \frac{1}{L_3} + \frac{1}{L_4}$$

Determine the total inductance of four coils connected in parallel. Each coil has an inductance of four Henrys.

$$\frac{1}{L_T} = \frac{1}{L_1} + \frac{1}{L_2} + \frac{1}{L_3} + \frac{1}{L_4}$$

$$\frac{1}{L_T} = \frac{1}{4} + \frac{1}{4} + \frac{1}{4} + \frac{1}{4}$$

$$\frac{1}{L_T} = \frac{4}{4} \text{ OR } L_T \times 4 = 1 \times 4 \text{ OR } L_T = \frac{4}{4} = 1 \text{ Henry}$$

An induction coil is a device, consisting of two concentric coils and an interrupter, that changes a low steady voltage into a high intermittent alternating voltage by electromagnetic induction. Most often used as a spark coil.



TO FIND IMPEDANCE

Impedance (Z):

Impedance is the total opposition to an alternating current presented by a circuit. Expressed in OHMS.

A When VOLTS AND AMPERES are known:

IMPEDANCE =
$$\frac{\text{VOLTS}}{\text{AMPERES}}$$
 OR Z = $\frac{\text{E}}{\text{I}}$

Determine the impedance of a 120 volt AC circuit that draws a current of four amperes.

$$Z = \frac{E}{I} = \frac{120}{4} = 30 \text{ OHMS}$$

B. When RESISTANCE AND REACTANCE are known:

$$Z = \sqrt{RESISTANCE^2 + REACTANCE^2} = \sqrt{R^2 + X^2}$$

Determine the impedance of an AC circuit when the resistance is 6 OHMS, and the reactance is 8 OHMS.

$$Z = \sqrt{R^2 + X^2} = \sqrt{36 + 64} = \sqrt{100} = 10 \text{ OHMS}$$

C. When RESISTANCE, INDUCTIVE REACTANCE, AND CAPACITIVE REACTANCE are known:

$$Z = \sqrt{R^2 + (X_L - X_C)^2}$$

Determine the impedance of an AC circuit that has a resistance of 6 OHMS, an inductive reactance of 18 OHMS, and a capacitive reactance of 10 OHMS.

$$Z = \sqrt{R^2 + (X_L - X_C)^2}$$

$$= \sqrt{6^2 + (18 - 10)^2} = \sqrt{6^2 + (8)^2}$$

$$= \sqrt{36 + 64} = \sqrt{100} = 10 \text{ OHMS}$$



TO FIND REACTANCE

Reactance (X):

Reactance in a circuit is the opposition to an alternating current caused by inductance and capacitance, equal to the difference between capacitive and inductive reactance. Expressed in OHMS.

A. INDUCTIVE REACTANCE X,

Inductive reactance is that element of reactance in a circuit caused by self-inductance.

Determine the reactance of a four-Henry coil on a 60 cycle, AC circuit.

$$X_L = 6.28 \times F \times L = 6.28 \times 60 \times 4 = 1507 \text{ OHMS}$$

B. CAPACITIVE REACTANCE X_c

Capacitive reactance is that element of reactance in a circuit caused by capacitance.

$$X_C = \frac{1}{2 \times 3.1416 \times FREQUENCY \times CAPACITANCE}$$

$$= \frac{1}{6.28 \times F \times C}$$

Determine the reactance of a four microfarad condenser on a 60 cycle, AC circuit.

$$X_{c} = \frac{1}{6.28 \times F \times C} = \frac{1}{6.28 \times 60 \times .000004}$$

$$= \frac{1}{0.0015072} = 663 \text{ OHMS}$$

A HENRY is a unit of inductance, equal to the inductance of a circuit in which the variation of a current at the rate of one ampere per second induces an electromotive force of one volt.

M

SYNCHRONOUS SPEED

Synchronous Speed (in RPM) = $\frac{120f}{P}$

f = frequency

P = poles per phase



SLIP

Slip (in RPM) = Synchronous speed - actual speed

Slip percentage = $\frac{\text{Synchronous speed - actual speed}}{\text{Synchronous speed}} \times 100$



LOCKED-ROTOR CURRENT THREE PHASE

 $LRC = \frac{1,000 \times HP \times kVA/HP}{V \times 1.732 \times PF \times eff}$

LRC = Locked rotor current, in amps

HP = Horsepower

V = Volts

PF = Power factor

eff = Motor efficiency

LOCKED-ROTOR CURRENT THREE PHASE

 $LRC = \frac{1,000 \times HP \times kVA/HP}{V \times 1.732 \times PF \times eff}$

LRC = Locked rotor current, in amps

HP = Horsepower


V = Volts

PF = Power factor

eff = Motor efficiency



MOTOR FRAMES



Motor frame dimensions are standardized, so that equipment and installation do not have to be customized around variable motor dimensions.



FRAME DIMENSIONS, IN INCHES

Frame No.	U	٧	D	E	F	M & N	Keyway
42	3/8	-	25/8	13/4	27/32	41/32	- 1
48	1/2	-	2	21/8	13/8	53/8	= 11
56	5/8	-	31/2	27/16	11/2	61/8	3/16, 3/32
66	3/4	_	41/8	215/16	21/2	77/8	3/16, 3/32
143 T	7/8	2	31/2	23/4	2	61/2	3/16, 3/32
145 T	7/8	2	31/2	23/4	21/2	7	3/16, 3/32
182 T	11/8	21/2	41/2	33/4	21/4	73/4	1/4, 1/8
184 T	11/8	21/2	41/2	33/4	23/4	81/4	1/4, 1/8
213 T	13/8	31/8	51/4	41/4	23/4	95/8	5/16, 5/32
215 T	13/8	31/8	51/4	41/4	31/2	103/8	5/16, 5/32
254 T	15/8	33/4	61/4	5	41/8	123/8	3/8, 3/16
256 T	15/8	33/4	61/4	5	5	131/4	3/8, 3/16
284 T	17/8	43/8	7	51/2	43/4	141/8	1/2, 1/4
286 T	17/8	43/8	7	51/2	51/2	147/8	1/2, 1/4
324 T	21/8	5	8	61/4	51/4	153/4	1/2, 1/4
326 T	21/8	5	8	61/4	6	161/2	1/2, 1/4
364 T	23/8	55/8	9	7	55/8	173/8	5/8, 5/16
365 T	2³/ ₈	5 ⁵ / ₈	9	7	61/8	177/8	5/8, 5/16
404 T	27/8	7	10	8	61/8	20	3/4, 3/8
405 T	27/8	7	10	8	67/8	203/4	3/4, 3/8
444 T	33/8	81/4	11	9	71/4	231/4	7/8, 7/16
445 T	33/8	81/4	11	9	81/4	241/4	7/8, 7/16



FRAME LETTER DESIGNATIONS

G	Gasoline pump motor
K	Sump pump motor
М	Oil burner motor
N	Oil burner motor
S	Short shaft or direct connection
T	Standard dimensions
U	Old designation – standard dimensions
Υ	Special dimensions required
Z	Shaft extension




INSULATION CLASSES

Class	°C
A	105
В	130
F	155
Н	180

Class	°F
A	221
В	266
F	311
Н	356




120/240 Volt Single-Phase Three-Wire System



- † Line one ungrounded conductor colored Black.
- † Line two ungrounded conductor colored Red.
- ** Grounded neutral conductor colored White or Gray.


120/240 Volt Three-Phase Four-Wire System (Delta High Leg)



- † A phase ungrounded conductor colored Black.
- †* B phase ungrounded conductor colored **Orange** or tagged (High Leg). (Caution 208V Orange to White)
- † C phase ungrounded conductor colored Red.
- ** Grounded conductor colored White or Gray. (Center tap)
- ** Grounded conductors are required to be white or gray or three white stripes. See *NEC* 200.6A.
- * B phase of high leg delta must be Orange or tagged.
- † Ungrounded conductor colors may be other than shown; see local ordinances or specifications.

COMMON ELECTRICAL DISTRIBUTION SYSTEMS


120/208 Volt Three-Phase Four-Wire System (WYE Co



- † A phase ungrounded conductor colored Black.
- † B phase ungrounded conductor colored Red.
- † C phase ungrounded conductor colored Blue.

** • Grounded neutral conductor colored White or Gray.

277/480 Volt Three-Phase Four-Wire System (WYE Connected)



- † A phase ungrounded conductor colored Brown.
- † B phase ungrounded conductor colored Orange.
- † C phase ungrounded conductor colored Yellow.
- * Grounded neutral conductor colored Gray.
- ** Grounded conductors are required to be white or gray or three white stripes. See NEC 200.6A.
- *B phase of high leg delta must be Orange or tagged.
- †Ungrounded conductor colors may be other than shown; see local ordinances or specifications.

VOLTAGE DROP CALCULATIONS, INDUCTANCE NEGLIGIBLE

Vd = Voltage Drop

I = Current in Conductor (Amperes)

L = One-way Length of Circuit (Ft.)

Cm = Cross Section Area of Conductor (Circular Mils)

K = Resistance in ohms of one circular mil foot of conductor

K = 12.9 for Copper Conductors at 75°C

K = 21.2 for Aluminum Conductors at 75°C

NOTE: K value changes with temperature.

See NEC Chapter 9, Table 8, Notes

Single-Phase Circuits:

 $Vd = \frac{2K \times L \times I}{Cm}$

or

 ${^*Cm} = \frac{2K \times L \times I}{Vd}$

Three-Phase Circuits:

 $Vd = \frac{1.73K \times L \times I}{Cm}$

or

 $^*Cm = \frac{1.73K \times L \times I}{Vd}$

^{*} NOTE: Always check ampacity tables to ensure conductors' ampacity is equal to load after voltage drop calculation.

DISTANCE (ONE-WAY) FOR 2% VOLTAGE DROP FOR 120 or 240 VOLTS - SINGLE PHASE (60°C insulation & terminals)

AMPS	VOLTS	12 AWG	10 AWG	8 AWG	6 AWG	4 AWG	3 AWG	2 AWG	1	1/0 AWG
20	120	30	48	77	122	194	245	309	389	491
TEN	240	60	96	154	244	388	490	618	778	982
30	120		32	51	81	129	163	206	260	327
	240		64	102	162	258	326	412	520	654
40	120			38	61	97	122	154	195	246
	240			76	122	194	244	308	390	492
50	120				49	78	98	123	156	196
- Fin	240				98	156	196	246	312	392
60	120					65	82	103	130	164
60	240					130	164	206	260	328
70	240					111	140	176	222	281
80	240						122	154	195	246
90	240							137	173	218
100	240								156	196

See footnotes on the next page concerning circuit load limitations.



Typical Voltage Drop Values Based on Conductor Size and One-Way Length* (60°C Termination and Insulation)

			TO THE REAL PROPERTY.		FEET				
Serien T	100	12 AWG	10 AWG	8 AWG	6 AWG	4 AWG	3 AWG	2 AWG	1 AWG
AMPERES	20	1.98	1.24	0.78	0.49	0.31	0.25	0.19	0.15
	30		1.86	1.17	0.74	0.46	0.37	0.29	0.23
	40			1.56	0.98	0.62	0.49	0.39	0.3
186	50	2000 (SV)	A STORY OF		1.23	0.77	0.61	0.49	0.39
	60					0.93	0.74	0.58	0.46
					FEET				
		12 AWG	10 AWG	8 AWG	6 AWG	4 AWG	3 AWG	2 AWG	1 AWG
AMPERES	20	3.95	2.49	1.56	0.98	0.62	0.49	0.39	0.31
	30	1.00	3.73	2.34	1.47	0.93	0.74	0.58	0.46
	40			3.13	1.97	1.24	0.98	0.78	0.62
	50				2.46	1.55	1.23	0.97	0.77
	60					1.85	1.47	1.17	0.92
				75	FEET				
		12 AWG	10 AWG		6 AWG	4 AWG	3 AWG	2 AWG	1 AWG
AMPERES	20	5.93	3.73	2.34	1.47	0.93	0.74	0.58	0.46
7.1111 =11.00	30	0,00	5.59	3.52	2.21	1.39	1.10	0.87	0.69
	40	200000000000000000000000000000000000000	0.00	4.69	2.95	1.85	1.47	1.17	0.92
	50	000000000000000000000000000000000000000	GREST TORREST	4.03	3.69	2.32	1.84	1.46	1.18
	60	0/22/00/00/00/00	CONTRACTOR OF STREET	200000000000000000000000000000000000000	3.09	2.78	2.21	1.75	1.39
	00					2.70	2,21	1.70	1.00
					FEET				
		12 AWG	10 AWG		6 AWG	4 AWG	3 AWG	2 AWG	1 AWG
AMPERES	20	7.90	4.97	3.13	1.97	1.24	0.98	0.78	0.62
	30	200200000	7.46	4.69	2.95	1.85	1.47	1.17	0.92
	40			6.25	3.93	2.47	1.96	1.56	1,23
	50	0.50	1983		4.92	3.09	2.45	1.94	1.54
	60	4				3.71	2.94	2.33	1.85
				125	FEET				
		12 AWG	10 AWG	8 AWG	6 AWG	4 AWG	3 AWG	2 AWG	1 AWG
AMPERES	20	9.88	6.21	3.91	2.46	1.55	1.23	0.97	0.77
	30	CANDED S	9.32	5.86	3.69	2.32	1.84	1.46	1.16
	40		110	7.81	4.92	3.09	2.45	1.94	1.54
	50		500000000000000000000000000000000000000		6.15	3.86	3.06	2.43	1.93
	60					4.64	3.68	2.92	2.3
			18						
		12 AWG	10 AWG	150 8 AWG	6 AWG	4 AWG	3 AWG	2 AWG	1 AWG
AMPERES	20		7.46	4.69	2.95	1.85	1.47	1.17	0.92
AMPERES	20	11.85		CONTRACTOR OF STREET					
	30		11.18	7.03	4.42	2.78	2.21	1.75	1.39
	40	Silver Survey		9.38	5.90	3.71	2.94	2.33	1.85
	50				-7.37	4.64	3.68	2.92	2.31
	60					5.56	4.41	3.50	2.77

A two-wire 20 ampere circuit using 12 AWG with a one-way distance of 25 feet will drop 1.98 volts;

120 volts - 1.98 volts = 118.02 volts as the load voltage.

240 volts - 1.98 volts = 238.02 volts as the load voltage.

* Better economy and efficiency will result using the voltage drop method on page 44.

A continuous load cannot exceed 80% of the circuit rating.

A motor or heating load cannot exceed 80% of the circuit rating.



VOLTAGE DROP CALCULATION EXAMPLES

Single-Phase Voltage Drop

What is the voltage drop of a 240 volt single-phase circuit consisting of #8 THWN copper conductors feeding a 30 ampere load that is 150 feet in length?

Voltage Drop Formula

$$Vd = \frac{2K \times L \times I}{Cm} = \frac{2 \times 12.9 \times 150 \times 30}{16,510} = \frac{116,100}{16,510} = 7 \text{ Volts}$$

Percentage voltage drop = 7 volts/240 volts = .029 = 2.9%

Voltage at load = 240 volts - 7 volts = 233 volts

Three-Phase Voltage Drop

What is the voltage drop of a 480 volt three-phase circuit consisting of 250 kcmil THWN copper conductors that supply a 250 ampere load that is 500 feet from the source?

Voltage Drop Formula

250 kcmil = 250,000 circular mils

$$Vd = \frac{1.73K \times L \times I}{Cm} = \frac{1.73 \times 12.9 \times 500 \times 250}{250,000} = \frac{2,789,625}{250,000} = 11 \text{ Volts}$$

Percentage voltage drop = 11 volts/480 volts = .0229 = 2.29%

Voltage at load = 480 volts - 11 volts = 469 volts

NOTE: Always check ampacity tables for conductors selected.



For Use with Open-Type Three-Phase Sixty-Cycle Induction Motors

	3600	RPM	1800	RPM	1200	RPM
MOTOR RATING HP	MAXIMUM CAPACITOR RATING KVAR	REDUCTION IN LINE CURRENT %	MAXIMUM CAPACITOR RATING KVAR	REDUCTION IN LINE CURRENT %	MAXIMUM CAPACITOR RATING KVAR	REDUCTION IN LINE CURRENT %
10 15 20 25 30	3 4 5 6 7	10 9 9 9	3 4 5 6 7	11 10 10 10 9	3.5 5 6.5 7.5 9	14 13 12 11 11
40 50 60 75	9 12 14 17	8 8 8	9 11 14 16	9 9 8 8	11 13 15 18	10 10 10 10
100 125 150 200	22 27 32.5 40	8 8 8 8	21 26 30 37.5	8 8 8 8	25 30 35 42.5	9 9 9

<u> </u>	900	RPM	720	RPM	600	RPM
MOTOR RATING HP	MAXIMUM CAPACITOR RATING KVAR	REDUCTION IN LINE CURRENT %	MAXIMUM CAPACITOR RATING KVAR	REDUCTION IN LINE CURRENT %	MAXIMUM CAPACITOR RATING KVAR	REDUCTION IN LINE CURRENT %
10	5	21	6.5	27	7.5	31
15	6.5	18	8	23	9.5	27
20	7.5	16	9	21	12	25
25	9	15	11	20	14	23
30	10	14	12	18	16	22
40	12	13	15	16	20	20
50	15	12	19	15	24	19
60	18	11	22	15	27	19
75	21	10	26	14	32.5	18
100	27	10	32.5	13	40	17
125	32.5	10	40	13	47.5	16
150	37.5	10	47.5	12	52.5	15
200	47.5	10	60	12	65	14

NOTE: If capacitors of a lower rating than the values given in the table are used, the percentage reduction in line current given in the table should be reduced proportionately.



POWER-FACTOR CORRECTION

TABLE VALUES × KW OF CAPACITORS NEEDED TO CORRECT FROM EXISTING TO DESIRED POWER FACTOR

EXISTING POWER FACTOR	CORRECTED POWER FACTOR									
%	100%	95%	90%	85%	80%	75%				
50 52 54 55 56 58 60 62 64 65 66 68 70 72 74 75 76 78 80 82 84 85 86 88 90 92 94 95	1.732 1.643 1.558 1.518 1.479 1.404 1.333 1.265 1.201 1.168 1.139 1.078 1.020 0.964 0.909 0.882 0.855 0.802 0.750 0.698 0.646 0.620 0.594 0.540 0.426 0.363 0.329	1.403 1.314 1.229 1.189 1.150 1.075 1.004 0.936 0.872 0.839 0.810 0.749 0.691 0.635 0.580 0.553 0.526 0.473 0.421 0.369 0.317 0.291 0.265 0.211 0.156 0.097 0.034	1.247 1.158 1.073 1.033 0.994 0.919 0.848 0.780 0.716 0.683 0.654 0.593 0.535 0.479 0.424 0.397 0.370 0.317 0.265 0.213 0.161 0.135 0.109 0.055	1.112 1.023 0.938 0.898 0.859 0.784 0.713 0.645 0.581 0.548 0.519 0.458 0.400 0.344 0.289 0.262 0.235 0.182 0.130 0.078	0.982 0.893 0.808 0.768 0.729 0.654 0.583 0.515 0.451 0.418 0.389 0.328 0.270 0.214 0.159 0.132 0.105 0.052	0.850 0.761 0.676 0.636 0.597 0.522 0.451 0.383 0.319 0.286 0.257 0.196 0.138 0.082 0.027				

TYPICAL PROBLEM: With a load of 500 KW at 70% power factor, it is desired to find the KVA of capacitors required to correct the power factor to 85%

SOLUTION: From the table, select the multiplying factor 0.400 corresponding to the existing 70%, and the corrected 85% power factor. $0.400 \times 500 = 200$ KVA of capacitors required.

POWER FACTOR AND EFFICIENCY EXAMPLE

A squirrel-cage induction motor is rated 10 horsepower, 208 volt, three phase and has a nameplate rating of 27.79 amperes. A wattmeter reading indicates 8 kilowatts of consumed (true) power. Calculate apparent power (KVA), power factor, efficiency, internal losses, and size the capacitor in kilovolts reactive (KVAR) needed to correct the power factor to unity (100%).

Apparent input power: kilovolt-amperes (KVA)

 $KVA = (E \times I \times 1.73) / 1000 = (208 \times 27.79 \times 1.73) / 1000 = 10 \text{ KVA}$

Power factor (PF) = ratio of true power (KW) to apparent power (KVA). Kilowatts / kilovolt-amperes = 8 KW/10 KVA = .8 = **80% Power Factor** 80% of the 10-KVA apparent power input performs work.

Motor output in kilowatts = 10 horsepower \times 746 watts = 7460 watts = **7.46 KW**.

Efficiency = watts out/watts in = 7.46 KW / 8 KW = .9325 = 93.25% **Efficiency**.

Internal losses (heat, friction, hysteresis) = 8 KW - 7.46 KW = **.54 KW** (540 watts)

Kilovolt-amperes reactive (KVAR) (Power stored in motor magnetic field)

KVAR =
$$\sqrt{\text{KVA}^2 - \text{KW}^2}$$
 = $\sqrt{10 \text{ KVA}^2 - 8 \text{ KW}^2}$ = $\sqrt{100 - 64}$ = $\sqrt{36}$ = **6 KVAR**

The size capacitor needed to equal the motor's stored reactive power is 6 KVAR. (A capacitor stores reactive power in its electrostatic field).

POWER FACTOR AND EFFICIENCY EXAMPLE

The power source must supply the current to perform work and maintain the motor's magnetic field. Before power factor correction, this was 27.79 amperes. The motor magnetizing current after power factor correction is supplied by circulation of current between the motor and the electrostatic field of the capacitor and is no longer supplied by power source after initial start up.

The motor feeder current after correction to 100% will equal the amount required by the input watts in this case $(8 \text{ KW} \times 1000) / (208 \text{ volts} \times 1.73)$ = 22.23 amps

- Kilo = (1000 example: 1000 watts = 1 kilowatt)
- Inductive loads (motors, coils) have lagging currents and capacitive loads have leading currents.
- Inductance and capacitance have opposite effects in a circuit and can cancel each other out.



LOCKED-ROTOR CODE LETTERS

Letter Code	Kilovolt-Ampere per Horsepower with Locked Rotor	Letter Code	Kilovolt-Ampere per Horsepower with Locked Rotor
Α	0 - 3.14	L	9.0 - 9.99
В	3.15 - 3.54	М	10.0 - 11.19
C	3.55 - 3.99	N	11.2 - 12.49
D	4.0 - 4.49	Р	12.5 - 13.99
E	4.5 - 4.99	The state of the s	14.0 - 15.99
F	5.0 - 5.59	S	16.0 - 17.99
G	5.6 - 6.29	Т	18.0 - 19.99
Н	6.3 - 7.09	U	20.0 - 22.39
J	7.1 - 7.99	V	22.4 and up
K	8.0 - 8.99	nul period	

The National Electrical Code® requires that all alternating current motors rated 1/2 horsepower or more (except for polyphase wound-rotor motors) must have code letters on their nameplates indicating motor input with locked rotor (in kilovolt-amperes per horsepower). If you know the horsepower and voltage rating of a motor and its "Locked KVA per Horsepower" (from above table), you can calculate the locked-rotor current using the following formulas.



LOCKED-ROTOR CODE LETTERS

Single-Phase Motors:


Locked-Rotor Current =
$$\frac{HP \times KVA_{hp} \times 1000}{E}$$


Three-Phase Motors:

Locked-Rotor Current =
$$\frac{\text{HP} \times \text{KVA}_{\text{hp}} \times 1000}{\text{E} \times 1.73}$$

Example: What is the maximum locked-rotor current for a 480 volt 25 horsepower code letter F motor? (from the table on page 52, code letter F = 5.59 KVA_{hp})

$$I = \frac{\text{HP} \times \text{KVA}_{hp} \times 1000}{\text{E} \times 1.73} = \frac{25 \times 5.59 \times 1000}{480 \times 1.73} = 168.29 \text{ Amperes}$$





NOTES:

- 1. The most important part of any motor is the nameplate. Check the data given on the plate before making the connections.
- 2. To change rotation direction of three-phase motor, swap any 2 T-leads.

NEMA ENCLOSURE TYPES NONHAZARDOUS LOCATIONS


The purpose of this document is to provide general information on the definitions of NEMA Enclosure Types to architects, engineers, installers, inspectors and other interested parties. [For more detailed and complete information, NEMA Standards Publication 250-2003, "Enclosures for Electrical Equipment (1000 Volts Maximum)" should be consulted.]

In Nonhazardous Locations, the specific enclosure types, their applications, and the environmental conditions they are designed to protect against, when completely and properly installed, are as follows:

- Type 1 Enclosures constructed for indoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment and to provide a degree of protection against falling dirt.
- Type 2 Enclosures constructed for indoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment, to provide a degree of protection against falling dirt, and to provide a degree of protection against dripping and light splashing of liquids.
- Type 3 Enclosures constructed for either indoor or outdoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment; to provide a degree of protection against falling dirt, rain, sleet, snow, and windblown dust; and that will be undamaged by the external formation of ice on the enclosure.
- Type 3R Enclosures constructed for either indoor or outdoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment; to provide a degree of protection against falling dirt, rain, sleet, and snow; and that will be undamaged by the external formation of ice on the enclosure.

NEMA ENCLOSURE TYPES NONHAZARDOUS LOCATIONS

- **Type 3S** Enclosures constructed for either indoor or outdoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment; to provide a degree of protection against falling dirt, rain, sleet, snow, and windblown dust; and in which the external mechanism(s) remain operable when ice laden.
- **Type 4 -** Enclosures constructed for either indoor or outdoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment; to provide a degree of protection against falling dirt, rain, sleet, snow, windblown dust, splashing water, and hose-directed water; and that will be undamaged by the external formation of ice on the enclosure.
- **Type 4X** Enclosures constructed for either indoor or outdoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment; to provide a degree of protection against falling dirt, rain, sleet, snow, windblown dust, splashing water, hose-directed water, and corrosion; and that will be undamaged by the external formation of ice on the enclosure.
- **Type 5 -** Enclosures constructed for indoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment; to provide a degree of protection against falling dirt; against settling airborne dust, lint, fibers, and flyings; and to provide a degree of protection against dripping and light splashing of liquids.
- **Type 6 -** Enclosures constructed for either indoor or outdoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment; to provide a degree of protection against falling dirt; against hose-directed water and the entry of water during occasional temporary submersion at a limited depth; and that will be undamaged by the external formation of ice on the enclosure.



- Type 6P Enclosures constructed for either indoor or outdoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment; to provide a degree of protection against falling dirt; against hose-directed water and the entry of water during prolonged submersion at a limited depth; and that will be undamaged by the external formation of ice on the enclosure.
- Type 12 Enclosures constructed (without knockouts) for indoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment; to provide a degree of protection against falling dirt; against circulating dust, lint, fibers, and flyings; and against dripping and light splashing of liquids.
- Type 12K Enclosures constructed (with knockouts) for indoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment; to provide a degree of protection against falling dirt; against circulating dust, lint, fibers, and flyings; and against dripping and light splashing of liquids.
- Type 13 Enclosures constructed for indoor use to provide a degree of protection to personnel against incidental contact with the enclosed equipment; to provide a degree of protection against falling dirt; against circulating dust, lint, fibers, and flyings; and against the spraying, splashing, and water, oil, and noncorrosive coolants.

NEMA ENCLOSURE TYPES HAZARDOUS LOCATIONS

In hazardous locations, when completely and properly installed and maintained, Type 7 and Type 10 enclosures are designed to contain an internal explosion without causing an external hazard. Type 8 enclosures are designed to prevent combustion through the use of oil-immersed equipment. Type 9 enclosures are designed to prevent the ignition of combustible dust.

- **Type 7 -** Enclosures constructed for indoor use in hazardous locations classified as Class I, Division 1, Groups A, B, C, or D as defined in *NFPA 70*.
- **Type 8 -** Enclosures constructed for either indoor or outdoor use in hazardous locations classified as Class I, Division 1, Groups A, B, C, or D as defined in *NFPA 70*.
- **Type 9 -** Enclosures constructed for indoor use in hazardous conditions classified as Class II, Division 1, Groups E, F, or G as defined in *NFPA 70*.
- **Type 10 -** Enclosures constructed to meet the requirements of the Mine Safety and Health Administration, 30 CFR, Part 18.



U.S. WEIGHTS AND MEASURES

Linear Measures

1 INCH = 2.540 CENTIMETERS

12 INCHES = 1 FOOT = 3.048 DECIMETERS 3 FEET = 1 YARD = 9.144 DECIMETERS

5.5 YARDS = 1 ROD = 5.029 METERS

40 RODS = 1 FURLONG = 2.018 HECTOMETERS

8 FURLONGS = 1 MILE = 1.609 KILOMETERS

Mile Measurements

1 STATUTE MILE = 5,280 FEET

1 SCOTS MILE = 5.952 FEET

1 IRISH MILE = 6,720 FEET

1 RUSSIAN VERST = 3.504 FEET

1 ITALIAN MILE = 4.401 FEET

1 SPANISH MILE = 15,084 FEET

Other Linear Measurements

1 HAND = 4 INCHES 7.92 INCHES 1 LINK

1 FATHOM = 6FEET 1 SPAN = 9 INCHES

1 CHAIN = 22 YARDS 1 FURLONG = 10CHAINS

> 1 CABLE = 608 FEET



U.S. WEIGHTS AND MEASURES

Square Measures

144 SQUARE INCHES = 1 SQUARE FOOT

SQUARE FEET = 1 SQUARE YARD

301/4 SQUARE YARDS = 1 SQUARE ROD

RODS = 1 ROOD40 ROODS = 1 ACRE 4

640 ACRES = 1 SQUARE MILE

= 1 SECTION 1 SQUARE MILE

SECTIONS = 1 TOWNSHIP

Cubic or Solid Measures

1 CU. FOOT = 1728 CU. INCHES

= 27 CU. FEET CU. YARD

1 CU. FOOT = 7.48 GALLONS 1 GALLON (WATER) = 8.34 LBS.

1 GALLON (U.S.) = 231 CU. INCHES OF WATER

1 GALLON (IMPERIAL) = 2771/4 CU. INCHES OF WATER



U.S. WEIGHTS AND MEASURES

Liquid Measurements

1 PINT = 4 GILLS

1 QUART = 2 PINTS

1 GALLON = 4 QUARTS

1 FIRKIN = 9 GALLONS (ALE OR BEER)

1 BARREL = 42 GALLONS (PETROLEUM OR CRUDE OIL)

Dry Measures

1 QUART = 2 PINTS

1 PECK = 8 QUARTS

1 BUSHEL = 4 PECKS

S I

U.S. WEIGHTS AND MEASURES

Weight Measurements (Mass)

A. Avoirdupois Weight:

1 OUNCE = 16 DRAMS 1 POUND = 16 OUNCES 1 HUNDREDWEIGHT = 100 POUNDS 1 TON = 2000 POUNDS

B. Troy Weight:

1 CARAT = 3.17 GRAINS 1 PENNYWEIGHT = 20 GRAINS

1 OUNCE = 20 PENNYWEIGHTS

1 POUND = 12 OUNCES

1 LONG HUNDRED-

WEIGHT = 112 POUNDS

1 LONG TON = 20 LONG HUNDREDWEIGHTS

= 2240 POUNDS

C. Apothecaries Weight:

1 SCRUPLE = 20 GRAINS = 1.296 GRAMS 1 DRAM = 3 SCRUPLES = 3.888 GRAMS 1 OUNCE = 8 DRAMS = 31.1035 GRAMS 1 POUND = 12 OUNCES = 373.2420 GRAMS

D. Kitchen Weights and Measures:

1 U.S. PINT = 16 FL. OUNCES 1 STANDARD CUP = 8 FL. OUNCES

1 TABLESPOON = 0.5 FL. OUNCES (15 CU. CMS.) 1 TEASPOON = 0.16 FL. OUNCES (5 CU. CMS.)



METRIC SYSTEM

Prefixes:

- A. MEGA = 1,000,000 E. DECI = 0.1 = 1000 F. CENTI = 0.01 B. KILO
- C. HECTO = 100 G. MILLI = 0.001
- D. DEKA = 10 H. MICRO = 0.000001

Linear Measures:

(THE UNIT IS THE METER = 39.37 INCHES)

- 1 CENTIMETER = 10
- MILLIMETERS = 0.3937011 IIV.

 CENTIMETERS = 3.9370113 INS. 1 DECIMETER = 10
- = 10 DECIMETERS 1 METER = 1.0936143 YDS.
 - 3.2808429 FT.
- 1 DEKAMETER = 10 METERS = 10.936143 YDS.
- DEKAMETERS = 109.36143 1 HECTOMETER = 10 YDS.
- HECTOMETERS = 0.62137 1 KILOMETER = 10 MILE
- 1 MYRIAMETER = 10,000 METERS


Square Measures:

(THE UNIT IS THE SQUARE METER = 1549.9969 SQ. INCHES)

- 1 SQ. CENTIMETER = 100 SQ. MILLIMETERS = 0.1550 SQ. IN.
- 1 SQ. DECIMETER = 100 SQ. CENTIMETERS = 15.550 SQ. INS.
- 1 SQ. METER = 100 SQ. DECIMETERS = 10.7639 SQ. FT.
- 1 SQ. DEKAMETER = 100 SQ. METERS = 119.60 SQ. YDS.
- 1 SQ. HECTOMETER = 100 SQ. DEKAMETERS
- 1 SQ. KILOMETER = 100 SQ. HECTOMETERS

(THE UNIT IS THE "ARE" = 100 SQ. METERS)

- = 10 MILLIARES = 10.7643 1 CENTIARE SQ. FT.
- 1 DECIARE = 10 CENTIARES = 11.96033 SQ. YDS.
- = 10 DECIARES = 119.6033 1 ARE SQ. YDS.
- = 10 ARES = 0.247110 ACRES 1 DEKARE
- 1 HEKTARE = 10 DEKARES = 2.471098 ACRES
- 1 SQ. KILOMETER = 100 HEKTARES = 0.38611 SQ. MILE



Cubic Measures:

(THE UNIT IS THE "STERE" = 61,025.38659 CU. INS.)

1 DECISTERE = 10 CENTISTERES = 3.531562 CU. FT. 1 STERE = 10 DECISTERES = 1.307986 CU. YDS.

1 DEKASTERE = 10 STERES = 13.07986 CU. YDS.

(THE UNIT IS THE METER = 39.37 INCHES)

1 CU. CENTIMETER = 1000 CU. MILLIMETERS = 0.06102 CU. IN.

1 CU. DECIMETER = 1000 CU. CENTIMETERS = 61.02374 CU. IN.

1 CU. METER = 1000 CU. DECIMETERS = 35.31467 CU. FT.

= 1.30795 CU. YDS. = 1 STERE

1 CU. CENTIMETER (WATER) = 1 GRAM 1000 CU. CENTIMETERS (WATER) = 1 LITER = 1 KILOGRAM

1 CU. METER (1000 LITERS) = 1 METRIC TON



METRIC SYSTEM

Measures of Weight:

(THE UNIT IS THE GRAM = 0.035274 OUNCES)

1 MILLIGRAM = 0.015432 GRAINS

1 CENTIGRAM = 10 MILLIGRAMS = 0.15432 GRAINS

1.5432 GRAINS 1 DECIGRAM = 10 CENTIGRAMS =

= 15.4323 GRAINS = 10 DECIGRAMS 1 GRAM

= 5.6438 DRAMS 1 DEKAGRAM = 10 GRAMS

1 HECTOGRAM = 10 DEKAGRAMS = 3.5274 OUNCES

1 KILOGRAM = 10 HECTOGRAMS = 2.2046223 POUNDS

22.046223 POUNDS 1 MYRIAGRAM = 10 KILOGRAMS =

1 QUINTAL = 10 MYRIAGRAMS = 1.986412 CWT.

1 METRIC TON = 10 QUINTAL = 2.2045.622 POUNDS

1 GRAM = 0.56438 DRAMS

= 1.77186 GRAMS 1 DRAM

= 27.3438 GRAINS

1 METRIC TON = 2,204.6223 POUNDS



Measures of Capacity:

(THE UNIT IS THE LITER = 1.0567 LIQUID QUARTS)

1 CENTILITER = 10 MILLILITERS = 0.338 FLUID OUNCES

1 DECILITER = 10 CENTILITERS = 3.38 FLUID OUNCES

1 LITER = 10 DECILITERS = 33.8 FLUID OUNCES

1 DEKALITER = 10 LITERS = 0.284 BUSHEL

1 HECTOLITER = 10 DEKALITERS = 2.84 BUSHELS

1 KILOLITER = 10 HECTOLITERS = 264.2 GALLONS

NOTE: $\frac{KILOMETERS}{8} \times 5 = MILES$ or $\frac{MILES}{5} \times 8 = KILOMETERS$

				N	ETRI	C DE	SIGN	ATO	R	nen		
12	16	21	27	35	41	53	63	78	91	103	129	155
3/8	1/2	3/4	1	11/4	11/2	2	21/2	3	31/2	4	5	6

U.S. Weights and Measures/Metric Equivalent Chart

	In.	Ft.	Yd.	Mile	mm	cm	m	km
1 Inch =	1	.0833	.0278	1.578x10 ⁻⁵	25.4		.0254	2.54x10 ⁻⁵
1 Foot =	12	1	.333	1.894x10 ⁻⁴	304.8		200000000000000000000000000000000000000	3.048x10-4
1 Yard =	36	3	1	5.6818 x10-4	914.4	0.0000000000000000000000000000000000000		9.144x10 ⁻⁴
1 Mile =	63,360	5280	1760	1	1,609,344	160,934.4		
1 mm =	.03937	.0032808	1.0936x10 ⁻³	6.2137x10 ⁻⁷	1	0.1	0.001	0.000001
1 cm =	.3937	.0328084	.0109361	6.2137x10 ⁻⁶	10	1	0.01	0.00001
1 m =	39.37	3.28084	1.09361	6.2137x10 ⁻⁴	1000	100	1	0.001
1 km =	39,370	3,280.84	1,093.61	0.62137	1,000,000		1000	1

In. = Inches Ft. = Foot Yd. = Yard Mi. = Mile mm = Millimeter cm = Centimeter m = Meter km = Kilometer

Explanation of Scientific Notation:

Scientific Notation is simply a way of expressing very large or very small numbers in a more compact format. Any number can be expressed as a number between 1 and 10, multiplied by a power of 10 (which indicates the correct position of the decimal point in the original number). Numbers greater than 10 have positive powers of 10, and numbers less than 1 have negative powers of 10.

Example: $186,000 = 1.86 \times 10^5$ $0.000524 = 5.24 \times 10^{-4}$



Useful Conversions/Equivalents

1	BTURa	ises 1 lb of water 1°F
1	GRAM CALORIERa	ises 1 gram of water 1°C
1	CIRCULAR MIL Eq	uals 0.7854 sq. mil
1	SQ. MILEq	uals 1.27 cir. mils

1 MIL Equals 0.001 in.

To determine circular mil of a conductor:

ROUND CONDUCTORCM = (Diameter in mils)²

BUS BAR CM = Width (mils) x Thickness (mils)

0.7854

NOTES:

1 Millimeter = 39.37 Mils

1 Cir. Millimeter = 1550 Cir. Mils


1 Sq. Millimeter = 1974 Cir. Mils



DECIMAL EQUIVALENTS

FRACTION					DECIMAL
1/64					.0156
2/64	1/32				.0313
3/64					.0469
4/64	2/32	1/16			.0625
5/64					.0781
6/64	3/32				.0938
7/64					.1094
8/64	4/32	2/16	1/8		.125
9/64					.1406_
10/64	5/32				.1563
11/64					.1719
12/64	6/32	3/16			.1875
13/64					.2031
14/64	7/32				.2188
15/64					.2344
16/64	8/32	4/16	2/8	1/4	.25
17/64					.2656
18/64	9/32				.2813
19/64					.2969
20/64	10/32	5/16			.3125
21/64					.3281
22/64	11/32				.3438
23/64					.3594
24/64	12/32	6/16	3/8	8.0	.375
25/64					.3906
26/64	13/32				.4063
27/64					.4219
28/64	14/32	7/16			.4375
29/64					.4531
30/64	15/32				.4688
31/64					.4844
32/64	16/32	8/16	4/8	2/4	.5

Decimals are rounded to the nearest 10,000th.




FRACTION					DECIMAL
33/64					.5156
34/64	17/32				.5313
35/64					.5469
36/64	18/32	9/16			.5625
37/64					.5781
38/64	19/32				.5938
39/64					.6094
40/64	20/32	10/16	5/8		.625
41/64					.6406
42/64	21/32				.6563
43/64					.6719
44/64	22/32	11/16			.6875
45/64					.7031
46/64	23/32				.7188
47/64					.7344
48/64	24/32	12/16	6/8	3/4	.75
49/64					.7656
50/64	25/32				.7813
51/64					.7969
52/64	26/32	13/16			.8125
53/64					.8281
54/64	27/32				.8438
55/64					.8594
56/64	28/32	14/16	7/8		.875
57/64			The second		.8906
58/64	29/32				.9063
59/64					.9219
60/64	30/32	15/16			.9375
61/64					.9531
62/64	31/32				.9688
63/64					.9844
64/64	32/32	16/16	8/8	4/4	1.000

Decimals are rounded to the nearest 10,000th.



SINGLE-PHASE MOTORS

SPLIT-PHASE—SQUIRREL-CAGE—DUAL-VOLTAGE



CLASSES OF SINGLE-PHASE MOTORS:

- 1. SPLIT-PHASE
 - A. CAPACITOR-START
 - B. REPULSION-START
 - C. RESISTANCE-START
 - D. SPLIT-CAPACITOR
- 2. COMMUTATOR
 - A. REPULSION
 - B. SERIES

TERMINAL COLOR MARKING:

T, BLUE

T₃ ORANGE

T₅ BLACK

T2 WHITE

T₄ YELLOW

T₈ RED

NOTE: Split-phase motors are usually fractional horsepower. The majority of electric motors used in washing machines, refrigerators, etc. are of the split-phase type.

To change the speed of a split-phase motor, the number of poles must be changed.


- 1. Addition of running winding
- 2. Two starting windings, and two running windings
- Consequent pole connections




SINGLE-PHASE MOTORS


SPLIT-PHASE—SQUIRREL-CAGE

A. RESISTANCE START:




Centrifugal switch (CS) opens after reaching 75% of normal speed.





B. CAPACITOR START:



NOTES:

1. A resistance start motor has a resistance connected in series with the starting winding.

2. The capacitor start motor is employed where a high starting torque is required.



DIRECT-CURRENT MOTORS



TERMINAL MARKINGS:


Terminal markings are used to tag terminals to which connections are to be made from outside circuits.

Facing the end opposite the drive (commutator end) the standard direction of shaft rotation is counter-clockwise.

A-1 and A-2 indicate armature leads.


S-1 and S-2 indicate series-field leads.

F-1 and F-2 indicate shunt-field leads.




SHUNT-WOUND MOTORS

To change rotation, reverse either armature leads or shunt leads. <u>Do not</u> reverse both armature and shunt leads.



SERIES-WOUND MOTORS

To change rotation, reverse either armature leads or series leads. <u>Do not</u> reverse both armature and series leads.



COMPOUND-WOUND MOTORS

To change rotation, reverse either armature leads or both the series and shunt leads.

<u>Do not reverse all three sets of leads.</u>

MOTE: Standard rotation for DC generator is clockwise.



MOTOR SELECTION CHECKLIST

- Horsepower requirements
- 2. Torque requirements
- 3. Speed requirements
- 4. Position (vertical, horizontal, etc.)
- 5. Conditions (temperature, water, corrosion, dust, etc.)
- 6. Operating cycle
- 7. Direction of rotation
- 8. Endplay
- 9. Available voltage, phases, frequency
- 10. Available starting current
- 11. Power factor concerns

74




MOTOR SELECTION CRITERIA

- Enclosures. Must be suitable to area of installation, but enclosed motors are more expensive for both purchase and operation.
- Torque. Motor's torque must exceed maximum torque requirements of the load. High-slip motors are preferred where there will be frequent peaks in required torque.
- 3. <u>Load cycle</u>. If loads cycle regularly, an average load (by RMS method) may be assumed, with a safety margin.
- 4. Loading. Motors operate most efficiently when fully loaded.
- Ambient temperatures. Motors are designed for an ambient operating temperature of 40°C. Each 10° above this will halve the life of types A & B winding insulation.



TYPICAL LOAD SERVICE FACTORS


Load	Service Factor
Pump – centrifugal	1.0
Pump – centrifugal, sewage	2.0
Pump – rotary	mu laria 1.5 d e la 1891 la
Pump – reciprocating	2.0
Fan – light-duty	1.0
Fan – centrifugal	1.5
Blower – centrifugal	1.0
Blower – vane	1.25
Compressor – centrifugal	1.25
Compressor – vane	1.5
Elevator – bucket	2.0
Elevator – freight	2.25
Conveyor	1.5
Conveyor – heavy use	2.0
Punch press	2.25
Extruder – plastic	2.0
Extruder – metal	2.5
Concrete mixer	2.0
Printing press	1.5
Woodworking machines	1.0



- Determine the size of an overcurrent protection device, sized for the largest motor.
- Add size determined in step 1 to the full-load amperage of all other motors.
- 3. The group overcurrent device for the motor feeder may be no larger than the amperage arrived at in step 2.

See NEC sections:

- 430.62(A) on overcurrent devices
- 430.24 on feeders
- 366.22 on gutters (if necessary)



- Determine the size of an overcurrent protection device, based upon the largest motor.
- 2. Add the sum of all other loads to size determined in step 1.
- 3. The group overcurrent device may be no larger than the amperage arrived at in step 2.

See NEC sections:

- 430.62(A) on overcurrent devices
- 215.2(A)(1) on feeders
- 250.142(B) on sub-panels
- 240.6(A) on overcurrent device sizes

78



DETERMINING OVERLOAD SIZE

- 1. Find motor full-load amps.
- 2. Add 25% (to achieve 125% total).
- 3. Choose overloads based upon step 2.

Example: If full-load current is 60 amps, overloads must be chosen based upon 60×1.25 , or 75 amps.

See NEC sections:

- 430.6(A)(2) on full-load currents
- 430.32(A)(1) on adding 25%



DETERMINING CONTROLLER SIZE

- Determine horsepower size of motor.
- Controller may have a horsepower rating no less than horsepower size of motor.

See NEC sections:

- 430.83(A)(1) on controllers
- · 430.110(A) on disconnecting means

80



MOTORS 2 HORSEPOWER OR LESS AND 300 VOLTS OR LESS

Switches may be used as controllers provided:

- A general use switch can be used if it is rated for at least twice the full-load current of the motor.
- AC switches on AC circuits may be used if the switch is rated 125% of the full-load current of the motor.

See NEC sections:

- 430.83(C)(1) on general use switches
- 430.83(C)(2) on AC switches

81



DETERMINING CONDUCTOR SIZES FOR SINGLE-PHASE MOTORS

- 1. Find motor full-load amps.
- 2. Add 25% to full-load amps (to achieve 125%).
- 3. Conductor must have an ampacity no lower than determined in step 2.
- 4. Select conductors from NEC Table 310.16.

See NEC sections:

- 430.6(A)(1) on full-load currents
- · 430.22(A) on adding 25%
- 310.10, FPN(2) on conductors

82



DETERMINING CONDUCTOR SIZES FOR ADJUSTABLE SPEED DRIVES

- 1. Determine rated input of power conversion equipment.
- 2. Add 25% (to achieve 125%) of rated current.
- 3. Select conductors from NEC Table 310.16.

See NEC sections:

- 430.122(A) on adjustable speed drive conductors
- 430.2 on variable speed motors



MOTOR AND MOTOR-CIRCUIT CONDUCTOR PROTECTION

Motors can have large starting currents three to five times or more than that of the actual motor current. In order for motors to start, the motor and motor circuit conductors are allowed to be protected by circuit breakers and fuses at values that are higher than the actual motor and conductor ampere ratings. These larger overcurrent devices do not provide overload protection and will only open upon short circuits or ground faults. Overload protection must be used to protect the motor based on the actual nameplate amperes of the motor. This protection is usually in the form of heating elements in manual or magnetic motor starters. Small motors such as waste disposal motors have a red overload reset button built into the motor.



- Use Full-Load Current from tables instead of nameplate.
- Branch-Circuit Conductors Use 125% of Full-Load Current to find conductor size.
- Branch-Circuit OCP Size Use percentages given in tables for Full-Load Current.
- Feeder Conductor Size 125% of largest motor and sum of the rest.
- · Feeder OCP Use largest OCP plus rest of Full-Load Currents.



General Motor Applications

Branch-Circuit Conductors: Use Full-Load Three-Phase Currents; From *NEC* Table 430.250,

50 HP 480 Volt Three-Phase motor design B, 75 degree terminations = 65 Amperes

125% of Full-Load Current [NEC 430.22(A)]

125% of 65 A = 81.25 Amperes Conductor Selection Ampacity

Branch-Circuit Overcurrent Device: *NEC* 430.52 (C1) (Branch-Circuit Short Circuit and Ground-Fault Protection) Use percentages given in 2005 *NEC* 430.52 for **Type** of circuit breaker or fuse used.

50 HP 480 V 3 Ph Motor = 65 Amperes.

Nontime Fuse = 300%.

300% of 65A = 195 A. *NEC* 430.52(C1)(EX1) Next size allowed *NEC* 240.6A = 200 Ampere Fuse.

MOTOR BRANCH CIRCUIT AND FEEDER EXAMPLE

Feeder Connectors: For 50 HP and 30 HP 480 Volt Three-Phase design B motors on same feeder

Use 125% of largest full-load current and 100% of rest. (*NEC* 430.24) 50 HP 480 V 3 Ph Motor = 65A; 30 HP 480 V 3 Ph Motor = 40A (125% of 65A) + 40A = **121.25 A** Conductor Selection Ampacity

Feeder Overcurrent Device: [NEC 430.62(A)]

(Feeder short circuit and ground-fault protection)

Use largest overcurrent protection device <u>plus</u> full-load currents of the rest of the motors.


50 HP = 200 A fuse (65 FLC)

30 HP = 125 A fuse (40 FLC)

200 A fuse + 40 A (FLC) = 240 A. Do not exceed this value on feeder. Go down to a **225 A** fuse.




APPROXIMATE TORQUE FIGURES, COMPOUND DC MOTORS




Speed and torque are inversely proportional; as one rises, the other falls.




HEATER CORRECTIONS FOR AMBIENT TEMPERATURES



100% is standardized at 104°F (40°C). Electrical components must be protected from excess heat.






A standard AC motor may never reach synchronous speed. As it approaches synchronous speed, torque falls to zero and rotation slows.



APPROXIMATE TORQUE FIGURES, WOUND ROTOR MOTORS



Torque peaks at higher percentages of synchronous speed, but falls to zero as synchronous speed is approached.



SIZING LOAD CONDUCTORS FROM GENERATORS

- 1. Determine generator output current from nameplate.
- 2. Add 15% (to achieve 115%) to generator current.
- 3. Select conductors from NEC Table 310.16.

See NEC sections:

- 445.13 on conductor ampacity
- 445.13, exception, on an exception to the 15% adder
- 310.10, FPN(2) on conductors

ELECTRICAL SAFETY DEFINITIONS

Arc Flash - The sudden release of heat energy and intense light at the point of an arc. Can be considered a short circuit through the air, usually created by accidental contact between live conductors.

Arc Blast - A pressure wave created by the heating, melting, vaporization, and expansion of conducting material and surrounding gases of air.

Arc Gap - The distance between energized conductors or between energized conductors and ground. Shorter arc gaps result in less energy being expended in the arc, while longer gaps reduce arc current. For 600 volts and below, arc gaps of 1.25 inches (32 mm) typically produce the maximum incident energy.

Approach Boundaries - Protection boundaries established to protect personnel from shock.

Calorie - The amount of heat needed to raise the temperature of 1 gram of water by 1° Celsius. 1 cal/cm² is equivalent to the exposure on the tip of a finger by a cigarette lighter for 1 second.

Distance to Arc - Refers to the distance from the receiving surface to the arc center. The value used for most calculations is typically 18 inches.

Electrically Safe Work Condition - Condition where the equipment and or circuit components have been disconnected from electrical energy sources, locked/tagged out, and tested to verify all sources of power are removed.

ELECTRICAL SAFETY DEFINITIONS

Exposed Live Parts - An energized conductor or part that is capable of being inadvertently touched or approached (nearer than a safe distance) by a person. It is applicable to parts that are not in an electrically safe work condition, suitably grounded, isolated, or insulated.

Flame Resistant (FR) - A term referring to fabric and its ability to limit the ignition or burning of the garment. It can be a specific characteristic of the material or a treatment applied to a material.

Flash Hazard Analysis - A study that analyzes potential exposure to Arc-Flash hazards. The outcome of the study establishes Incident Energy levels, Hazard Risk Categories, Flash Protection Boundaries, and required PPE. It also helps define safe work practices.

Flash Protection Boundary - A protection boundary established to protect personnel from Arc-Flash hazards. The Flash Protection Boundary is the distance at which an unprotected worker can receive a second-degree burn to bare skin.

Flash Suit - A term referring to a complete FR rated Personal Protective Equipment (PPE) system that would cover a person's body, excluding the hands and feet. Included would be pants, shirt/jacket, and flash hood with a built-in face shield.

Hazard Risk Category - A classification of risks (from 0–4) defined by NFPA 70E. Each category requires PPE and is related to incident energy levels.



Incident Energy - The amount of thermal energy impressed on a surface generated during an electrical arc at a certain distance from the arc. Typically measured in cal/cm².

PPE - An acronym for Personal Protective Equipment. It can include clothing, tools, and equipment.

Qualified Person - A person who is trained and knowledgeable on the construction and operation of the equipment and can recognize and avoid electrical hazards that may be encountered.

Shock - A trauma subjected to the body by electrical current. When personnel come in contact with energized conductors, it can result in current flowing through their body, often causing serious injury or death.

Unqualified Person - A person who does not possess all the skills and knowledge or has not been trained for a particular task.

Ŋ

ELECTRICAL SAFETY CHECKLIST

- Deenergize the equipment whenever possible prior to performing any work.
- Verify you are "qualified" and properly trained to perform the required task.
- Identify the equipment and verify you have a clear understanding and have been trained on how the equipment operates.
- 4. Provide justification why the work must be performed in an "energized" condition (if applicable).
- 5. Identify which safe work practices will be used to insure safety.
- 6. Determine if a Hazard Analysis has been performed to identify all hazards (Shock, Arc Flash, etc.).
- Identify protection boundaries for Shock (Limited, Restricted & Prohibited Approach) and Arc Flash (Flash Protection Boundary).
- Identify the required Personal Protective Equipment (PPE) for the task to be performed based on the Hazard Risk Category (HRC) and available incident Energy (cal/cm²).
- 9. Provide barriers or other means to prevent access to the work area by "unqualified" workers.
- 10. Perform a job briefing and identify job-or task-specific hazards.
- 11. Obtain written management approval to perform the work in an "energized" condition (where applicable).

ELECTRICAL SAFETY LOCKOUT-TAGOUT PROCEDURES

OSHA requires that energy sources to machines or equipment must be turned off and disconnected isolating them from the energy source. The isolating or disconnecting means must be either locked or tagged with a warning label. While lockout is the more reliable and preferred method, OSHA accepts tagout to be a suitable replacement in limited situations. NFPA 70E Article 120 contains detailed instructions for lockout—tagout and placing equipment in an electrically safe work condition.

Application of Lockout-Tagout Devices

- 1. Make necessary preparations for shutdown.
- 2. Shut down the machine or equipment.
- 3. Turn OFF (open) the energy isolating device (fuse/circuit breaker).
- 4. Apply the lockout or tagout device.
- Render safe all stored or residual energy.
- 6. Verify the isolation and deenergization of the machine or equipment.



Removal of Lockout-Tagout Devices

- Inspect the work area to ensure that nonessential items have been removed and that machine or equipment components are intact and capable of operating properly. Especially look for tools or pieces of conductors that may have not been removed.
- Check the area around the machine or equipment to ensure that all employees have been safely positioned or removed.
- 3. Make sure that only the employees who attached the locks or tags are the ones removing them.
- After removing locks or tags, notify affected employees before starting equipment or machines.

NOTE: For specific lockout-tagout procedures, refer to OSHA and NFPA 70E.



Nominal System	Limited Appro	ach Boundary	Restricted	Prohibited	
Voltage (Phase to Phase)	Exposed Fixed Circuit Part	Exposed Movable Conductor	Approach Boundary	Approach Boundary	
50 to 300 V	10 ft. 0 in.	3 ft. 6 in.	Avoid Contact	Avoid Contact	
301 to 750 V	10 ft. 0 in.	3 ft. 6 in.	1 ft. 0 in.	0 ft. 1 in.	
751 V to 15 kV	10 ft. 0 in.	5 ft. 0 in.	2 ft. 2 in.	0 ft. 7 in.	
15.1 kV to 36 kV	10 ft. 0 in.	6 ft. 0 in.	2 ft. 7 in.	0 ft. 10 in.	
36.1 kV to 46 kV	10 ft. 0 in.	8 ft. 0 in.	2 ft. 9 in.	1 ft. 5 in.	
46.1 kV to 72.5 kV	10 ft. 0 in.	8 ft. 0 in.	3 ft. 2 in.	2 ft. 1 in.	
72.6 kV to 121 kV	10 ft. 8 in.	8 ft. 0 in.	3 ft. 3 in.	2 ft. 8 in.	

NOTE: Data derived from NFPA 70E Table 130.2(C)


Shock protection boundaries are based on system voltage and whether the exposed energized components are fixed or movable. *NFPA 70E* Table 130.2(C) defines these boundary distances for nominal phase-to-phase system voltages from 50 Volts to 800 kV. Approach Boundary distances may range from an inch to several feet. Please refer to *NFPA 70E* Table 130.2(C) for more information.

Protection Boundaries:

Limited Approach: Qualified person or unqualified person if accompanied by qualified person. PPE is required.

Restricted Approach: Qualified persons only. PPE is required.

Prohibited Approach: Qualified persons only. Use PPE as if making direct contact with a live part.




The amount of heat energy (cal/cm²) at the distance shown. The incident energy determines the Hazard Risk Category.

equipment for which this label -

is produced.

The distance from exposed energized parts at which a 2nd degree burn can occur—to unprotected skin.

The NFPA 70E established Hazard Risk Category (see NFPA 70E Table 130.7(c)(11) for explanation) based on Incident Energy.



against voltage and shock hazard.

PULLEY CALCULATIONS


The most common configuration consists of a motor with a pulley attached to its shaft, connected by a belt to a second pulley. The motor pulley is referred to as the **Driving Pulley**. The second pulley is called the **Driven Pulley**. The speed at which the Driven Pulley turns is determined by the speed at which the Driving Pulley turns as well as the diameters of both pulleys. The following formulas may be used to determine the relationships between the motor, pulley diameters and pulley speeds.

D = Diameter of Driving Pulley

d1=Diameter of Driven Pulley

S = Speed of Driving Pulley (revolutions per minute)

s1=Speed of Driven Pulley (revolutions per minute)



• To determine the speed of the Driven Pulley (Driven RPM):

$$s^1 = \frac{D \times S}{d^1}$$
 or Driven RPM = $\frac{\text{Driving Pulley Dia.} \times \text{Driving RPM}}{\text{Driven Pulley Dia.}}$

To determine the speed of the Driving Pulley (Driving RPM):

$$s = \frac{d^1 \times s^1}{D}$$
 or Driving RPM = $\frac{\text{Driven Pulley Dia.} \times \text{Driven RPM}}{\text{Driving Pulley Dia.}}$

· To determine the diameter of the Driven Pulley (Driven Dia.):


$$d^1 = \frac{D \times S}{s^1}$$
 or Driven Dia. = $\frac{Driving Pulley Dia. \times Driving RPM}{Driven RPM}$

• To determine the diameter of the Driving Pulley (Driving Dia.):

$$D = \frac{d^1 \times s^1}{s} \quad \text{or} \quad \text{Driving Dia.} = \frac{\text{Driven Pulley Dia.} \times \text{Driving RPM}}{\text{Driving RPM}}$$



DETERMINING BELT LENGTH



D = Diameter of larger pulley

d = Diameter of smaller pulley

 $\pi = 3.1416$

x = Distance between shaft centers



HORSEPOWER CAPACITIES

Belt Speed (ft./min)	Pulley Diameter									
	1/2"	1"	11/2"	2"	3"	4"	6"			
1000	.33	.53	.66	.79	.92	.99	1.05			
2000	.99	1.32	1.38	1.45	1.65	1.78	1.91			
3000	1.25	1.58	1.98	2.17	2.59	2.70	2.90			
4000	1.51	1.91	2.44	2.77	3.17	3.43	3.76			
5000	1.65	2.11	2.77	3.10	3.63	3.96	4.42			
6000	1.71	2.31	3.03	3.36	3.96	4.42	4.95			
7000	1.71	2.37	3.16	3.56	4.29	4.88	5.54			
8000	1.65	2.44	3.30	3.69	4.49	4.55	5.87			
9000	1.51	2.50	3.36	3.76	4.55	4.62	6.07			
10,000	1.32	2.50	3.43	3.82	4.62	4.62	6.14			

MOTES:

Based on medium, Single-Ply, Dacron Belts per inch of width



GEAR SIZING

$$N = \frac{n \times R}{r}$$

$$n = \frac{N \times R}{r}$$

n = Number of teeth, driven gear

N= Number of teeth, driving gear

R= RPM, pinion

r = RPM, gear




DETERMINING SHAFT DIAMETER

Shaft diameter (in inches) = $\sqrt{\frac{K \times HP}{RPM}}$

HP = Horsepower transmitted

K = Constant, varying between 50 and 125, depending on shaft and distance between bearings



Output Torque

 $O_T = I_T \times R_R \times R_E$

Output Speed

$$O_S = \frac{I_S}{R_B} \times R_E$$

Output Horsepower

OHP = IHP × RE

 O_T = Output torque

IT = Input torque

R_B = Gear reduction ratio

 O_S = Output speed (RPM)

Is = Input speed (RPM)

R_E = Reducer efficiency

OHP = Output horsepower

 I_{HP} = Input horsepower



MOTOR TORQUE

Torque

$$T = \frac{HP \times 5252}{RPM}$$

Starting Torque

$$T = \frac{HP \times 5252 \times C}{RPM}$$

T = Torque, 1 lb-ft

HP = Horsepower

RPM = Rotations per minute

C = Motor class percentage

5252 is a constant, derived as follows: $\frac{33,000 \text{ 1 lb-ft}}{\pi \times 2} = 5252$



CALCULATING COST OF OPERATING AN ELECTRICAL APPLIANCE

What is the monthly cost of operating a 240 volt 5 kilowatt (kW) central electric heater that operates 12 hours per day, when the cost is 15 cents per kilowatt-hour (kWhr)?

Cost = Watts x Hours used x Rate per kWhr / 1000

5 kW = 5000 Watts

Hours = 12 hours x 30 days = 360 hours per month


= 5000 x 360 x .15 / 1000

= 270,000 / 1000 = \$270 Monthly cost

The above example is for a resistive load. Air-conditioning loads are primarily inductive loads. However, if ampere and voltage values are known this method will give an approximate cost. Kilowatt-hour rates vary for different power companies, and for residential use, graduated rate scales are usually used (the more power used, the lower the rate). Commercial and industrial rates are generally based on kilowatt usage, maximum demand, and power factor. Other costs are often added such as fuel cost adjustments.




ELECTRICAL SYMBOLS





ELECTRICAL SYMBOLS




NOTE: N.O. = Normally Open; N.C. = Normally Closed




WIRING DIAGRAMS

Basic Diagram of Two-Wire Control Circuit




Wiring Diagram of Starter (Two-Wire Control)




Reprinted from Miller, Charles R. NFPA's Pocket Electrical References, First Edition. Jones and Bartlett Publishers, 2007.



Control Circuit Only




Basic Three-Wire Control Circuit






WIRING DIAGRAMS

Wiring Diagram of Starter (Three-Wire Control)




Control Circuit Only




Reprinted from Miller, Charles R. NFPA's Pocket Electrical References, First Edition. Jones and Bartlett Publishers, 2007.

COMPLETE STOP-START SYSTEM WITH CONTROL TRANSFORMER




M = MOTOR STARTER COIL


NOTE: Controls and motor are of different voltages.






JOGGING WITH CONTROL RELAY






= MOTOR STARTER COIL


Jogging circuits are used when machines must be operated momentarily for inching (as in set-up or maintenance). The jog circuit allows the starter to be energized only as long as the jog button is depressed.



Multiple Start and Stop Stations




Start Push Button with Job Selector Switch







Reversing Starter with Limit Switches



Reversing Starter









TERMINAL DESIGNATIONS

Generators and Synchronous Motors




Terminal identifications are the same for both delta and wye, except that the wye arrangement includes a T_0 terminal, which connects to the center-point of the coils.

COUNTER-EMF STARTING DC Motors DC Supply




A counter-EMF opposes any change in current flow and is used to reduce high-starting currents.

TWO-SPEED STARTING




Note this circuit's interlocks:

- · Closing the fast switch also opens the Slow leg of the circuit.
- When the S coil is activated, it opens the normally closed S contact in the Fast leg of the circuit.
- When the F coil is activated, it opens the normally closed F contact in the Slow leg of the circuit.



Synchronous Motor



The auto-transformers are in the circuit for starting, and removed afterward.